


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OXY USA	Contact Kelton Beard
Address 1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O) 575-628-4100
Facility Name Indian Basin Station 133	Facility Type Production Facility

Surface Owner BLM	Mineral Owner	Lease No. 3001528813
-------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	33	21S	24E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15bbls	Volume Recovered 4bbls
Source of Release 6 inch tubing line	Date and Hour of Occurrence	Date and Hour of Discovery 11-22-09 @ 10:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour See above	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
6 inch tubing line rusted, causing the line to split

Describe Area Affected and Cleanup Action Taken.*

Area affected was on the location approx. 50' X 30'. A vac-truck was called to pick up all standing fluid remaining on location. Delineation was completed and all horizontal and vertical levels were below required levels. Groundwater is >100' BGS; Ranking Criteria is 0 points on well head protection and surface body of water protection. Site will be left as is. Lab analytical is in the original remediation plan that was submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Kelton Beard	Approved by District Supervisor:	
Title: HES Specialist	Approval Date: 7/13/15	Expiration Date: N/A
E-mail Address: kelton_beard@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 2-2-10		

* Attach Additional Sheets If Necessary

2 PD-727