

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUL 30 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1521254720

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit #156 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Unknown
API No. 30-015-35269	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	11	22S	28E	660	North	860	West	Eddy

Latitude 32.413266° Longitude -104.064294°

NATURE OF RELEASE

Type of Release Oil/Condensate	Volume of Release 41 bbls	Volume Recovered 0 bbls
Source of Release Tank	Date and Hour of Occurrence 7/20/2015 time unknown	Date and Hour of Discovery 7/20/2015 at 10 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD) and Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour 7/20/2015 at 12:26 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Corrosion caused a hole to form in tank. Tank was cleaned and repaired.

Describe Area Affected and Cleanup Action Taken.*
Leak affected 1950 square feet of caliche pad within the earthen berm. Leaked soaked through the earthen berm on the west side of the containment and affected a small area of caliche pad (area included above). The upper 3 to 10 inches of the most heavily impacted caliche was excavated by hand and removed to a disposal facility. The remaining impacted soils have been covered with plastic until delineation and remediation can be done.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Signed By <i>[Signature]</i> Approved by Environmental Specialist.	
Title: Assistant Remediation Foreman	Approval Date: 7/31/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/30/2015 Phone: 432-661-0571	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/31/15**

2RP-3176

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Thursday, July 30, 2015 2:32 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos@blm.gov; Savoie, Tony A.
Subject: Initial C-141 BOPCO Big Eddy Unit 156 Tank Leak (7-20-2015)
Attachments: BEU 156 Tank Leak (7-20-2015) Initial C-141.pdf; Initial Photo.jpg

Hello Everyone,
Small correction on the fluid lost from this tank since last email. Calculated at 41 bbls condensate/oil. It's on the form. Thanks!

From: Ruth, Amy C.
Sent: Monday, July 20, 2015 12:26 PM
To: Mike Bratcher; EMNRD Patterson Heather
Cc: jamos
Subject: BOPCO Big Eddy Unit 156

BOPCO personnel located this leak from the oil tank on location. A total of 54 bbls oil leaked into the earthen berm and no fluids have been recovered. A c-141 will be submitted.

Thank you,

Amy (432-661-0571)

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com>
To: "Ruth, Amy C." <ACRuth@BassPet.Com>, "Savoie, Tony A." <TASavoie@BassPet.Com>, "Blevins, Bradley" <BBlevins@BassPet.Com>, "Johnson, Steve F" <SJohnson@BassPet.Com>, "Hanna, Wesley W." <WWHanna@BassPet.Com>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: big eddy unit 156 bopco l.p.
Description: API: 3001535269
Latitude: 32.412960
Longitude: -104.064005

See a Map of <<http://maps.google.com/maps?saddr=&daddr=32.412960,-104.064005>> Carroll Caudill reported hole in oil tk. Contact him for details 575-706-8000. I am out of the office today.
[image1.jpeg]

Sent from my iPhone



Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Monday, July 20, 2015 12:26 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: jamos
Subject: BOPCO Big Eddy Unit 156
Attachments: image1.jpeg

BOPCO personnel located this leak from the oil tank on location. A total of 54 bbls oil leaked into the earthen berm and no fluids have been recovered. A c-141 will be submitted.

Thank you,

Amy (432-661-0571)

Sent from my iPhone

Begin forwarded message:

From: "Fuqua, D. Jace" <DJFuqua@BassPet.Com<mailto:DJFuqua@BassPet.Com>>
To: "Ruth, Amy C." <ACRuth@BassPet.Com<mailto:ACRuth@BassPet.Com>>, "Savoie, Tony A." <TASavoie@BassPet.Com<mailto:TASavoie@BassPet.Com>>, "Blevins, Bradley" <BBlevins@BassPet.Com<mailto:BBlevins@BassPet.Com>>, "Johnson, Steve F" <SJohnson@BassPet.Com<mailto:SJohnson@BassPet.Com>>, "Hanna, Wesley W." <WWHanna@BassPet.Com<mailto:WWHanna@BassPet.Com>>
Subject: Wellsite Share from Wellsite Navigator Pro iOS

The following Wellsite information and coordinates have been shared with you via Wellsite Navigator Pro iOS Edition.

Name: big eddy unit 156 bopco l.p.
Description: API: 3001535269
Latitude: 32.412960
Longitude: -104.064005

See a Map of <<http://maps.google.com/maps?saddr=&daddr=32.412960,-104.064005>>
hole in oil tk. Contact him for details 575-706-8000. I am out of the office today.
[image1.jpeg]

Carroll Caudill reported

Sent from my iPhone
[cid:5:688:0]