

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 30 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**NAB1521256674**      **OPERATOR**       Initial Report       Final Report

Name of Company Cimarex Energy	1021083	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX		Telephone No. 432-853-7059
Facility Name CP State Com #1		Facility Type P & A battery

Surface Owner	Mineral Owner	API No. 30-015-34120
---------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	19	17S	29E	1310	S	660	E	Eddy

Latitude 32.8164 Longitude -104.10775

**NATURE OF RELEASE**

Type of Release produced water	Volume of Release 60 bbls	Volume Recovered 59 bbls
Source of Release tank	Date and Hour of Occurrence 07/27/2015	Date and Hour of Discovery 07/27/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson/Mike Bratcher	
By Whom? Christine Alderman	Date and Hour 7/29/15 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

While removing old equipment from this P & A'd facility, a tank was about to be moved and workers didn't realize it still had some fluid in it. The release was contained within a LINED berm.

Describe Area Affected and Cleanup Action Taken.\*

This location is being reclaimed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: ESH Supervisor	Approval Date: 7/31/15	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: 7/30/2015      Phone: 432-853-7059		

\* Attach Additional Sheets If Necessary

2RP-3178

## Bratcher, Mike, EMNRD

---

**From:** Christine Alderman <calderman@cimarex.com>  
**Sent:** Thursday, July 30, 2015 10:43 AM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Gloria Garza  
**Subject:** FW: CP St Com #1 (30-015-34120)  
**Attachments:** 20150730103036570.pdf

Sorry! With attachment....

### Christine Alderman

***ESH Supervisor – Permian Basin***

Mobile: 432-853-7059

Office: 432-620-1982



---

**From:** Christine Alderman  
**Sent:** Wednesday, July 29, 2015 3:04 PM  
**To:** Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us); mike.bratcher@state.nm.us  
**Cc:** Gloria Garza  
**Subject:** CP St Com #1 (30-015-34120)

We had a release at the above named lease in Eddy Co. The equipment was being removed from the location to begin reclamation and a steel tank still had fluids in it. The tank had 60 bbls of Produced water which was released into a lined containment. All fluids were recovered.

A C-141 will follow. Thank you.

### Christine Alderman

***ESH Supervisor – Permian Basin***

Mobile: 432-853-7059

Office: 432-620-1982



## Bratcher, Mike, EMNRD

---

**From:** Christine Alderman <calderman@cimarex.com>  
**Sent:** Wednesday, July 29, 2015 2:04 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Gloria Garza  
**Subject:** CP St Com #1 (30-015-34120)

We had a release at the above named lease in Eddy Co. The equipment was being removed from the location to begin reclamation and a steel tank still had fluids in it. The tank had 60 bbls of Produced water which was released into a lined containment. All fluids were recovered.

A C-141 will follow. Thank you.

**Christine Alderman**

***ESH Supervisor – Permian Basin***

Mobile: 432-853-7059

Office: 432-620-1982

