

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1521756768

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Chase Settle
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Lost Tank AIS State #3 Battery	Facility Type Battery	
Surface Owner State	Mineral Owner State	API No. 30-015-26586

LOCATION OF RELEASE

Unit Letter N	Section 36	Township 21S	Range 31E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.42943 Longitude 103.73303

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 5 B/O & 25 B/PW	Volume Recovered 5 B/O & 25 B/PW
Source of Release Separator	Date and Hour of Occurrence 7/21/2015; AM	Date and Hour of Discovery 7/21/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Ian Dolly, Mathew Hagman, Mark Naranjo & Dana Strang	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 7/22/2015; 12:46 P.M. (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 4 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*
Describe Cause of Problem and Remedial Action Taken.*
A dump valve on a separator was stuck open, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 50' X 50' was affected within the unlined/bermed battery. The valves were closed and all of the crude oil and produced water was recovered (100%). A roustabout crew was called to make repairs on the separator. Impacted soils will be excavated /hauled to a NMOCD approved facility. **Depth to Ground Water: > 100' (approximately 110', per Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Settle	Approval Date: <u>8/5/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: CSettle@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: July 31, 2015	Phone: 575-748-4171	

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/10/15

2RP-3189

Patterson, Heather, EMNRD

From: Chase Settle <CSettle@yatespetroleum.com>
Sent: Tuesday, August 04, 2015 1:01 PM
To: Bratcher, Mike, EMNRD; idolly@slo.state.nm.us; dvstrang@slo.state.nm.us; mhagman@slo.state.nm.us; Naranjo, Mark M.; Patterson, Heather, EMNRD
Cc: Bob Asher; Katie Parker; Tanna Adams; Veronica Alvarado
Subject: Lost Tank AIS State #3 Battery C-141
Attachments: C-141 Lost Tank AIS State #3 Battery (Initial).pdf

Please find attached the C-141 Initial for the below listed location.

Lost Tank AIS State #3 Battery

30-015-26586
Section 36, T21S-R31E
660' FSL, 1980' FWL
Eddy County, New Mexico

Thank you,

Chase Settle, M.S.

Environmental Regulatory Agent
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From: Amber Cannon <ACannon@yatespetroleum.com>
Sent: Wednesday, July 22, 2015 12:46 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; NMSLO (Carlsbad/Ion Dolly); NMSLO (Hobbs/Mathew Hagman); Naranjo, Mark M.; NMSLO (Santa Fe/Dana Vackar Strang)
Cc: Bob Asher; Chase Settle; Katie Parker; Tanna Adams; Veronica Alvarado; IncidentReportingNM
Subject: Release Notification (Lost Tank AIS State #3 - Battery)

Yates Petroleum Corporation is reporting a release at the following location (7/22/2015, 9:25 AM).

Lost Tank AIS State #3 – Battery
30-015-26586
Section 36, T21S-R31E
660' FSL, 1980' FWL
Eddy County, New Mexico

Released: Approximately 25 B/PW, 5 B/O; Recovered: 25 B/PW, 5 B/O.

Cause of the release was from a dump valve that was stuck open. Vacuum truck(s) and clean-up crews were called. The release has been reported to have stayed inside of an unlined, bermed battery. A Form C-141 with complete information will be submitted.

Thanks,

Amber Griffin

Environmental Regulatory Agent
Yates Petroleum Corporation
Office: (575) 748-4111
Cell: (575) 513-8799

Amber Griffin

Environmental Regulatory Agent
Yates Petroleum Corporation
Office: (575) 748-4111
Cell: (575) 513-8799