

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522A39496

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>300737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 150	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 3001531538
------------------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	6	24S	30E	760		810		Eddy

Latitude: 32.25193 Longitude: 103.91479

NATURE OF RELEASE

Type of Release: Produced Water- Packer Fluid	Volume of Release: 11 barrels	Volume Recovered: None
Source of Release: Packer fluid containment overflowed	Date and Hour of Occurrence: 8-10-15 @ 4:30pm	Date and Hour of Discovery: 8-10-15 @ 4:45pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

NM OIL CONSERVATION
ARTESIA DISTRICT

AUG 11 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

BOPCO EHS was notified of a release that occurred at the PLU 150 location. A packing fluid containment overflowed, releasing 11 barrels of fluid to the ground surface. No fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted an area west of the wellhead on the caliche pad and a small portion of the interim reclamation/ pit area. No fluid was recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Bradley Blevins</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Bradley Blevins	Approval Date: <i>8/11/15</i>	Expiration Date: <i>N/A</i>
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	Attached <input type="checkbox"/>	
Date: <i>8-11-15</i> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/11/15

2RP-3197

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, August 11, 2015 1:51 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 150
Attachments: Initial C-141 Plu 150.pdf

All,

Please find the attached initial C-141 for the spill that occurred at the PLU 150. If you have any questions please let me know. Thanks,

Brad Blevins
Assistant Remediation Foreman
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com