

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1523130328

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>		Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329
Facility Name: PLU 315H Flowline		Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:	API No. 3001539166

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	13	24S	30E	1650		710		Eddy

Latitude: 32.20739 Longitude: 103.82718

NATURE OF RELEASE

Type of Release: Crude Oil and Produced Water	Volume of Release: 10 oil, 52 barrels PW	Volume Recovered: None
Source of Release: Flowline	Date and Hour of Occurrence: 8-14-15 @ 12:00am	Date and Hour of Discovery: 8-14-15 @ 1:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos vis Email	
By Whom? Bradley Blevins	Date and Hour: 8-14-15 @ 3:48pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 17 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The PLU 315H flowline failed, an area night pumper discovered the release. Bopco EHS was notified Friday morning and was able to respond and collect information. It was discovered that 52 barrels of produced water and 10 barrels of oil was released to the ground surface. No fluid was recovered, the majority of the release remained within the caliche lease road.

Describe Area Affected and Cleanup Action Taken.*

The majority of the release remained within the caliche lease road, no fluid was recoverable at the time of discovery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date:	Expiration Date:
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: <i>8-17-15</i> Phone: 432-214-3704	Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *9/21/15*

22P-3207

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Monday, August 17, 2015 12:27 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU 315H
Attachments: doc04506320150817112359.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU 315H. If you have any questions please let me know.

Thank you.

Brad Blevins
Remediation Foreman (PLU)
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com

Patterson, Heather, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Friday, August 14, 2015 3:48 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos
Cc: Blevins, Bradley
Subject: PLU 315 Flowline

All,
BOPCO EHS was notified of a release that occurred on the PLU 315 Flowline. 32.20739 103.82718. The Flowline failed at the road crossing and ran down the road an estimated two tenths of a mile. 62 barrels of oil and PW was estimated released with no recovery. I will follow up with and initial C-141. Thanks

Sent from my iPhone