

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB15232310A2**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <b>2100737</b>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit #74 Tank Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-22839	

**LOCATION OF RELEASE**

Unit Letter B	Section 25	Township 21S	Range 28E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.456689° Longitude -104.037531°

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 12 bbls	Volume Recovered 10 bbls
Source of Release Heater	Date and Hour of Occurrence 8/13/2015 time unknown	Date and Hour of Discovery 8/13/2015 11 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Heater began leaking from corroded bottom. The heater was drained, cleaned, and LOTO – will not be in use until it is removed from location		
Describe Area Affected and Cleanup Action Taken.* The leak affected approximately 545 square feet of caliche pad. A vacuum truck recovered standing fluids.		

**NM OIL CONSERVATION  
ARTESIA DISTRICT  
AUG 17 2015  
RECEIVED**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy Ruth	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <b>8/20/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 8/17/2015 Phone: 432-661-0571	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

**LATER THAN: 9/21/15**

\* Attach Additional Sheets If Necessary

**2RP-3213**

## **Patterson, Heather, EMNRD**

---

**From:** Ruth, Amy C. <ACRuth@BassPet.Com>  
**Sent:** Monday, August 17, 2015 2:40 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** jamos@blm.gov  
**Subject:** Initial C-141 BEU 74 Tank Battery leak 8-13-2015  
**Attachments:** Initial C-141 BEU 74 Tank Battery 8-13-15.pdf

Heater leak from corroded bottom. Drained and cleaned unit; LOTO until heater can be removed from site.



*Amy C. Ruth*  
BOPCO, L.P.  
EH&S Remediation Specialist  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office: (575)887-7329  
Fax: (575)887-7473  
Cell: (432)661-0571