

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

AUG 25 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1523931622

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production <i>DP/37</i>	Contact Daniel Suniga
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5850
Facility Name Ore Ida 14 Fed 10	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29290
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter I	Section 14	Township 24S	Range 29E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32°21'53.45"

Longitude: W 103°94'90.29"

NATURE OF RELEASE

Type of Release Spill Produced Water and Oil	Volume of Release 85 bbls	Volume Recovered 60 bbls
Source of Release Pump malfunction	Date and Hour of Occurrence 8/21/2015 @ 10:41 PM	Date and Hour of Discovery 8/21/2015 @ 10:41 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM OCD	
By Whom? David Simmons	Date and Hour August 21, 2015 @ 11:26 PM August 21, 2015 @ 11:31 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lease operator arrived at location and discovered that the water tank was over flowing causing an 85 bbl produced water and oil spill into lined containment. The pump was reset and within a minute the tank stopped from over flowing. Black River Trucking was called out and they were able to recover 60 bbls of produced water and oil.

Describe Area Affected and Cleanup Action Taken.*

Black River Trucking was called out and they were able to recover 60 bbls of produced water and oil. Environmental agency will be contacted for cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <i>Mike Beaman</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: corina.moya@dvn.com	Approval Date: <i>8/27/15</i>	Expiration Date: <i>N/A</i>
Date: 8/25/2015 Phone: 575.746.5559	Conditions of Approval:	Attached <input type="checkbox"/>
	Remediation per O.C.D. Rules & Guidelines	
	EMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *9/27/15*

2RP-3222

Bratcher, Mike, EMNRD

From: Moya, Corina <Corina.Moya@dvn.com>
Sent: Tuesday, August 25, 2015 4:16 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Jim Amos (jamos@blm.gov); stucker@blm.gov
Subject: Ore Ida 14 Fed 10_85 pw and oil spill 8.21.2015
Attachments: Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 pic 2 of 5.jpg; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 pic 3 of 5.jpg.jpeg; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 pic 4 of 5.jpg; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 pic 5 of 5.jpg; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 C-141.doc; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 GIS Mapping.pdf; Ore Ida 14 Fed 10_85 bbl produced water and oil spill 8.21.2015 pic 1 of 5.jpg

Good afternoon,

Please see attached C-141, pic and mapping for the Ore Ida 14 Fed 10 for 85 bbl pw and oil spill that occurred on 8.21.2015

Thank you,

Corina Moya
Field Admin Support
Production
B Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.