

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1303751618

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC <i>229/137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Skelly 737	Facility Type	Well pad

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-40095
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	17S	31E					Eddy

Latitude 32.82517 Longitude 103.86330

NATURE OF RELEASE

Type of Release Produced water
Source of Release buried produced water line

Volume of Release 100bbls
Date and Hour of Occurrence
10/09/2012

Volume Recovered 90bbls
Date and Hour of Discovery
10/09/2012 5:00 m.

Was Immediate Notice Given?

Yes No Not Required

If YES, To Whom?

Mike Bratcher-OCD
Terry Gregston-BLM
Jim Amos-BLM

By Whom? Josh Russo

Date and Hour 10/12/2012 8:53 a.m.

Was a Watercourse Reached?

Yes No

If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A produced water injection line was hit by a dozer while downsizing the Skelly 737 well pad. This flowline is owned by Linn Energy. The line has been repaired.

Describe Area Affected and Cleanup Action Taken.*

Initially 100bbls of produced water were released from the line and we were able to recover 90bbls with a vacuum truck. This spill was immediately contained utilizing the equipment onsite. Tetra Tech has sampled the spill area and we have removed the impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The act of a C-141 filed with the NMOCD marked as "Final Report" does not relieve the operator of liability.

NOV 02 2012

NMOCD ARIE