

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT Form C-141
Revised October 10, 2003
OCT 06 2014
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Oxy USA, Inc	Contact Dusty Wilson
Address 6 Desta Drive Suite 600, Midland, TX 79705	Telephone No. (432) 685-5771
Facility Name State 2 Well #2	Facility Type Flowline

Surface Owner: State	Mineral Owner	Lease No. NM4
----------------------	---------------	----------------------

LOCATION OF RELEASE

30-015-28416


Unit Letter P	Section 2	Township 22S	Range 31E	Feet from the 660	North/South Line South Line	Feet from the	East/West Line	County Eddy
-------------------------	---------------------	------------------------	---------------------	-----------------------------	---------------------------------------	---------------	----------------	-----------------------

Latitude N ° Longitude W °

NATURE OF RELEASE

Type of Release: Produced Water & Oil	Volume of Release 10 bbls oil 20 bbls water	Volume Recovered 0 bbls
Source of Release Flowline	Date and Hour of Occurrence 11/14/05 11:00a.m.	Date and Hour of Discovery 11-14-05 12:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom?	Date and Hour 11-14-05 1:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Flowline blew a hole in the middle of the pasture		
Describe Area Affected and Cleanup Action Taken.* Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez	Approved by District Supervisor: 	
Title: Project Manager	Approval Date: 7/27/15	Expiration Date: NA
E-mail Address: Ike.Tavarez@tetrattech.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 12/16/2013 Phone: (432) 687-8110		

Attach Additional Sheets If Necessary

2PP-3158