

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

AUG 28 2015
Submit to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1524328793

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	Contact Amber Griffin
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name Perdomo BMP State Com #1H	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-36499
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	24	24S	27E	1650	South	660	West	Eddy

Latitude 32.20029 Longitude 104.15024

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 42 B/O	Volume Recovered 40 B/O
Source of Release Production Tank	Date and Hour of Occurrence 8/19/2015; AM	Date and Hour of Discovery 8/19/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade, Ian Dolly, Mathew Hagman, Mark Naranjo, & Dana Strang	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 8/20/2015; 7:55 AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The choke on the well was washed out from the sand and the production tank overflowed, causing the release. The wells were shut in and vacuum trucks were called to recover the released fluids.

Describe Area Affected and Cleanup Action Taken.*

The release impacted areas inside and outside of the lined berm. Oil was recovered from within the berm and the gravel is being removed and replaced. Areas outside of the berm that were impacted were scraped and soils were hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken from the areas outside of the lined berm and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 20) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: < 50' (approximately 45', Section 24, T24S-R27E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Amber Griffin</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Amber Griffin	Approval Date: <u>8/31/15</u>	Expiration Date: <u>N/A</u>
Title: NM Environmental Regulatory Agent	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
E-mail Address: AGriffin@yatespetroleum.com	Attached <input type="checkbox"/>	
Date: August 26, 2015	Phone: 575-748-4111	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 10/2/15

2RP-3226

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Tanna Adams <TCAAdams@yatespetroleum.com>
Sent: Friday, August 28, 2015 11:48 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; idolly@slo.state.nm.us; mhagman@slo.state.nm.us; Naranjo, Mark M.; dvstrang@slo.state.nm.us
Cc: Bob Asher; Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Perdomo BMP State Com #1H C141
Attachments: Perdomo BMP State Com #1H_C141_Initial_081915.pdf

Please find attached the signed C141 Initial for the below listed location:

Perdomo BMP State Com #1H
30-015-36499
Section 24, T24S-R27E
1650 FSL & 660 FWL
Eddy County, New Mexico

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Technician
Environmental Department
Office: (575) 748-4184
TCAAdams@yatespetroleum.com



This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Thursday, August 20, 2015 7:55 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; NMSLO (Carlsbad/Ion Dolly); NMSLO (Hobbs/Mathew Hagman); Naranjo, Mark M.; NMSLO (Santa Fe/Dana Vackar Strang)
Cc: IncidentReportingNM; Amber Griffin; Chase Settle; Katie Parker; Tanna Adams; Veronica Alvarado
Subject: Release Notification (Perdomo BMP State Com. #1)

Yates Petroleum Corporation is reporting a release at the following location (8/19/2015, 11:00 AM).

Perdomo BMP State #1
30-015-36499
Section 24, T24S-R27E
1650 FSL & 660 FWL
Eddy County, New Mexico

Released: 42 B/O; Recovered: 40 B/O.

Cause of the release was from the chock on the well washed out, causing tank to fill up and overflow. High winds blew some oil onto the production pad. Vacuum truck(s) and roustabout crew(s) were called, line repaired. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
