

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 01 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1524531024

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>6137</i>		Contact Dan Suniga; Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 575-390-5850
Facility Name North Pure Gold 8 Federal 11		Facility Type Salt Water Disposal
Surface Owner Federal	Mineral Owner Federal	API No 30-015-32619

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	8	23S	31E	1400	South	1540	East	Eddy

Latitude: 32.31545

Longitude: -103.795859

NATURE OF RELEASE

Type of Release Produced water release	Volume of Release 20 BBLS	Volume Recovered 18 BBLS
Source of Release hole in high pressure hose on H pump	Date and Hour of Occurrence September 1, 2015 2:40 AM	Date and Hour of Discovery September 1, 2015 2:40 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM; Jim Amos OCD-Mike Bratcher	
By Whom? Assistant Production Foreman: David Simmons	Date and Hour BLM-September 1, 2015 4:40 AM OCD- September 1, 2015 2:10 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Hole in high pressure line on the H pump allowed 20 BBLS of produced water to be released. The power to the H pump and the charge pump was shut off and then the closed the valves upstream and downstream of the release to prevent further release. Line is being repaired.

Describe Area Affected and Cleanup Action Taken.*

20 BBLS of produced water was released. All of the released fluid remained on location. 18 BBLS of the released fluid was recovered via vacuum truck. Release occurred north of the water tanks. Approximate size of the affected area is 30' x 30'. Most of the released fluid collected in a hole that the produced water created when it released from the high pressure line. Environmental Agency will be contacted for remediation services.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: <i>9/2/15</i> Expiration Date: <i>N/A</i>
E-mail Address: sandy.farley@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9.1.15 Phone: 575.746.5587	Remediation per O.C.D. Rules & Guidelines	

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/2/15**

2RP-3233

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Tuesday, September 01, 2015 2:31 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Jim Amos (jamos@blm.gov); Shelly Tucker
Cc: Harris, Jacqui
Subject: North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15
Attachments: North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 GIS Image.pdf; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 pic 2 of 4-Night.jpg; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 pic 3 of 4-Night.jpg; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 pic 4 of 4-Night.JPG; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 pic 1 of 2-Day.JPG; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 pic 2 of 2-Day.jpeg; North Pure Gold 8 Fed 11 Release 20BBL PW 9.1.15 Initial C-141.doc

Good afternoon,

Attached is the Initial C-141, pictures and GIS Image for the 20 BBLs produced water release that occurred at the North Pure Gold 8 Fed 11 on September 1, 2015. The red dot on the GIS Image represents the approximate location of the release.

Have a terrific day

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.