

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources SEP 02 2015
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1524736913

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production Company <i>U137</i>	Contact Garry Michael; Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-4895
Facility Name Snapping 2 State 6H	Facility Type Oil Well
Surface Owner State	Mineral Owner State
API No 30-015-39162	

LOCATION OF RELEASE

Unit Letter O	Section 2	Township 26S	Range 31E	Feet from the 330	North/South Line South	Feet from the 2285	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.0657884 N

Longitude: 103.7476605 W

NATURE OF RELEASE

Type of Release air gas release	Volume of Release 182 MCF gas	Volume Recovered 0 MCF gas
Source of Release tee downstream from the choke	Date and Hour of Occurrence September 1, 2015 2:30 AM	Date and Hour of Discovery September 1, 2015 3:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Tee downstream of the choke was washed out causing a release of air gas. Both the flare and the well were shut in to prevent further release. Tee has been repaired.		
Describe Area Affected and Cleanup Action Taken.* Approximately 182 MCF air gas was released from the tee downstream of the choke. No further action required.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandy Farley	Signed By <i>Mike Beaudin</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>9/14/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>sandy.farley@dvn.com</i>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9-1-15 Phone: 575.746.5587		

* Attach Additional Sheets If Necessary

2 RP-3238

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dev.com>
Sent: Wednesday, September 02, 2015 9:10 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Harris, Jacqui
Subject: Snapping 2 State 6H 182 MCF Gas 9.1.15
Attachments: Snapping 2 State 6H 182 MCF Gas 9.1.15 Initial & Final C-141.doc; Snapping 2 State 6H 182 MCF Gas 9.1.15 GIS Image.pdf; Snapping 2 State 6H 182 MCF Gas 9.1.15 pic 1 of 2.JPG; Snapping 2 State 6H 182MCF Gas 9.1.15 pic 2 of 2.JPG

Good morning,

Attached is the Initial & Final C-141, GIS Image and pictures for the 182MCF air gas release that occurred at the Snapping 2 State 6H on September 1, 2015. The red dot on the GIS Image represents the approximate origin of release.

Have a terrific day

Sandra Farley
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.