

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Recd. 8/20/15  
NMOCID Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB 1524750307

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy Production <i>W137</i>	Contact Garry Michael
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 153H	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-38535	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	3	25 S	31 E	200	North	1980	East	Eddy

Latitude: N 32°16'62.16"

Longitude: W 103°76'35.73"

**NATURE OF RELEASE**

Type of Release Spill Oil	Volume of Release 40 bbls	Volume Recovered 35 bbls
Source of Release Suction Lines in the circulating pump where not closed	Date and Hour of Occurrence 7.19.2015 @ 4:00 AM	Date and Hour of Discovery 7.19.2015 @ 4:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM Mike Bratcher OCD	
By Whom? Eduardo Enriquez	Date and Hour 7.19.2015 @ 4:56 AM 7.19.2015 @ 4:58 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

On July 19, 2015 Pace Energy Lease Operator was driving by the Cotton Draw Unit 153 H at 4:00 AM when he noticed fluid on location. The fluid was coming from the suction lines in the circulating pump, Lease Operator proceeded to close the valves to stop the spill.

Describe Area Affected and Cleanup Action Taken.\*

Horizon trucking was called to recover 35 bbls. Further documentation to follow.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCID rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCID marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCID acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>8/14/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7.20.2015 Phone: 575.746.5559	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

\* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/4/15**

*2RP-3241*

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 7/19/15

Notice received by: [Signature]

Deem
Name of Company/Phone #

Callin Deem 153
Facility Name

30-06-38535
API #

3
Sec.

255-31e.
Township Range

7/15 @ 4:58pm
Date of Occurrence

7/19/15 4:00am
Date/Hour of Discovery

Oil
Type of Release

40 bbls
Volume of Release

35 bbls
Volume Recovered

Briefly Describe Cause of Problem and action taken:

Suction lines in the circulating pump were not closed.

Deem 575-513-9637
Notice given by: Name/ Company

7/19
Date/Hour Immediate Notice given

Date C-141 received: 8/20/15

2RP- 3241

\*\*\*\*\*

FLARE NOTIFICATION

Call-In Sheet

Date:

Notice received by:

Name of Company/Phone #

Facility Name

Date of Occurrence

Date/Hour of Flare

Type of Release

Flared MCF Volume

Volume Recovered

Briefly Describe Cause of Problem and action taken:

Notice given by: Name/ Company

Date/Hour Immediate Notice given

Date C-141 received:

2RP-