

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 08 2015

Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1525234198

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>0137</i>	Contact Garry Michael; Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 118H	Facility Type Oil Well

Surface Owner Federal	Mineral Owner Federal	API No 30-015-37362
------------------------------	------------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	26	24S	31E	330	North	1980	East	Eddy

Latitude: N 32°11'40.69"

Longitude: W 103°44'47.67"

NATURE OF RELEASE

Type of Release produced water release	Volume of Release 8BBLS	Volume Recovered 8BBLS
Source of Release water tank overflow	Date and Hour of Occurrence September 4, 2015 3:58 AM	Date and Hour of Discovery September 4, 2015 3:58 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM; Jim Amos OCD; Mike Bratcher	
By Whom? Assistant Production Foreman; David Simmons	Date and Hour BLM September 4, 2015 5:20 AM & OCD Mike Bratcher September 4, 2015 2:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully. N/A

Describe Cause of Problem and Remedial Action Taken.*

High tank levels caused produced water tank to overflow into surrounding lined containment. Well was immediately shut in to prevent further release and excess water was hauled off to reduce tank levels.

Describe Area Affected and Cleanup Action Taken.*

8 BBLS of produced water was released into surrounding lined containment. All the released fluid was recovered via vacuum truck. No holes were found in the liner. No further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: <i>9/11/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: sandy.farley@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9.8.15 Phone: 575.746.5587		

* Attach Additional Sheets If Necessary

Photos on file

2RP-3245

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Tuesday, September 08, 2015 2:14 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Harris, Jacqui
Subject: Cotton Draw Unit 118H PW Release 8BBLS 9.4.15
Attachments: Cotton Draw Unit 118H PW Release 8BBLS 9.4.15 Initial and Final C-141.doc; Cotton Draw Unit 118H PW Release 8BBLS 9.4.15 pic 1 of 3.jpg; Cotton Draw Unit 118H PW Release 8BBLS 9.4.15 pic 2 of 3.jpg; Cotton Draw Unit 118H PW Release 8BBLS 9.4.15 pic 3 of 3.jpg; Cotton Draw Unit 118H PW Release 8BBLS 9.4.15 GIS Image.pdf

Good afternoon,

Attached is the Initial and Final C-141, GIS Image and photos for the 8BBLS produced water release that occurred at the Cotton Draw Unit 118H on September 4, 2015. The blue dot on the GIS Image represents the approximate origin of the release.

Have a terrific afternoon

Sandra Farley

Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, New Mexico 88211
575 746 5587



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.