

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1526627950** OPERATOR  Initial Report  Final Report

Name of Company	RKI E&P, LLC <i>246289</i>	Contact	Zack Laird
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	405-987-2213
Facility Name:	North Brushy Draw Fed 35-6H	Facility Type :	Oil and Gas Well
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30-015-42293

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	25S	29E	175	FNL	2290	FEL	Eddy

Latitude: 32.0929574 Longitude: -103.95337

**NATURE OF RELEASE**

Type of Release: Drilling Mud/Frac Fluid	Volume of Release: 760 Bbls	Volume Recovered: 600 Bbls
Source of Release: 5.5" x 9.675" annulus	Date and Hour of Occurrence: 09/17/15 - 0200hrs MT	Date and Hour of Discovery: 09/17/15 - 0200hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson/Shelly Tucker (BIM)	
By Whom? Zack Laird	Date and Hour: 09/17/15 - 1000hrs and 1715hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* During stage 8 stimulation operations an unknown downhole failure (i.e. casing part) caused communication between 5.5" and 9.625" casing, pressure relief valve plumbed to "B" section of wellhead parted under pressure and allowed well flow on surface for approximately 1.5hrs.		
Describe Area Affected and Cleanup Action Taken.* Fluid accumulated on well pad and ran off location to the South for approximately .5 miles		

**NM OIL CONSERVATION**  
**ARTESIA DISTRICT**  
**SEP 17 2015**  
**RECEIVED**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zack Laird	Approved by Environmental Specialist:	
Title: Sr. EHS Manager	Approval Date: 9/23/15	Expiration Date: N/A
E-mail Address: Zlaird@rkixp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/17/15 Phone: 405-987-2213	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: 10/25/15</b>	

\* Attach Additional Sheets If Necessary

*2RP-3278*

## **Patterson, Heather, EMNRD**

---

**From:** Zackary Laird <ZLaird@rkixp.com>  
**Sent:** Thursday, September 17, 2015 4:19 PM  
**To:** stucker@blm.gov; Patterson, Heather, EMNRD  
**Cc:** Taylor Jones  
**Subject:** WPX E&P Spill Notification  
**Attachments:** NM\_NBD35-6H\_InitialC141\_Signed(091715).pdf

Shelly/Heather,

Please see attached OCD form C-141 for a spill occurring at the WPX(RKI) operated N Brushy Draw Federal 35-6H well in Eddy County, NM today (API # 30-015-42293).

Shelly, I was told that Tyke with WPX, contacted you earlier today and that you were able to walk the location with him, is that correct?

Please let me know if you have any questions.

Regards,

Zack Laird | Sr. EHS Manager

**WPX Energy, Inc.**

210 Park Avenue, Suite 700 | Oklahoma City, OK 73102

405.987.2213 (o) | 405.742.2696 (m) | ZLaird@rkixp.com

---

**This email is confidential. If you believe it has been sent to you in error, then do not read it, do not notify the sender you have received it, and delete it. Email transmissions cannot be warranted to be secure or error-free as information could be intercepted, misdirected, corrupted, lost, incomplete, destroyed or containing viruses. The sender therefore cannot guarantee the integrity or security of this email or any file(s) included herewith. RKI and the sender hereby disclaim any and all liability for injury or damages that may result from the recipient(s) receipt or transmission of this email and any file(s) included herewith or reliance on the contents thereof. Any oilfield equipment, materials or services ordered by or provided to RKI or its affiliates in connection with this message shall be governed by RKI's Terms and Conditions of Purchase ( a copy of which may be found at [www.rkixp.com](http://www.rkixp.com) ) and such Terms and Conditions of Purchase are hereby incorporated and expressly made a part hereof. A paper copy of RKI's Terms and Conditions of Purchase will be provided upon your written request.**