

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 21 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Send Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526650929

OPERATOR

Initial Report Final Report

| | | |
|--|-------------------------------|-------------------------|
| Name of Company Yates Petroleum Corporation | OGRID Number 25575 | Contact Robert Asher |
| Address 104 S. 4 th Street | Telephone No. 575-748-1471 | |
| Facility Name Quail BQL State Com #1H | Facility Type Battery | |

| | | |
|------------------------|------------------------|-------------------------|
| Surface Owner State | Mineral Owner State | API No. 30-015-38170 |
|------------------------|------------------------|-------------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| O | 2 | 26S | 30E | 330 | South | 1650 | East | Eddy |

Latitude 32.06531 Longitude 103.84832

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Produced Water | Volume of Release 16 B/PW | Volume Recovered 16 B/PW |
| Source of Release Production Tank | Date and Hour of Occurrence 8/27/2015; AM | Date and Hour of Discovery 8/27/2015; AM |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? N/A | |
| By Whom? N/A | Date and Hour N/A | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The water leg on the production tank was knocked down by the wind, causing the release. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 35' X 18' within the lined/bermed battery. The valves were closed and all of the produced water was recovered (100%). **Depth to Ground Water: > 100' (approximately 250', per Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on all released produced water recovered and the battery being lined and bermed, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|---|---|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Robert Asher | Approved by Environmental Specialist:  | |
| Title: NM Environmental Regulatory Supervisor | Approval Date: 9/23/15 | Expiration Date: N/A |
| E-mail Address: boba@yatespetroleum.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: September 21, 2015 | Phone: 575-748-4217 | 2RP- |

* Attach Additional Sheets If Necessary

2RP-3289

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAadams@yatespetroleum.com>
Sent: Monday, September 21, 2015 1:49 PM
To: Bratcher, Mike, EMNRD
Cc: Bob Asher; Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Quail BQL State Com #1H C141
Attachments: Quail BQL State Com #1H_C141_InitialFinal_082715.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

**Quail BQL State Com #1H
30-015-38170
Section 2, T26S-R30E
330 FSL & 1650 FEL
Eddy County, New Mexico**

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Technician
Environmental Department
Office: (575) 748-4184
TCAadams@yatespetroleum.com



This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
