

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1527234118

OPERATOR Initial Report Final Report

Name of Company: Mewbourne Oil Company <i>14744</i>	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Tamano 11 NC Fed #1H	Facility Type: Producing Oil Well
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-41350	

LOCATION OF RELEASE

Unit Letter N	Section 11	Township 18S	Range 31E	Feet from the 150'	North/South Line South	Feet from the 2310'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.7552376 Longitude -103.84127

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls total fluid	Volume Recovered: 15 bbl Oil
Source of Release: Stuffing Box/ Well head	Date and Hour of Occurrence 9-25-15	Date and Hour of Discovery 9-25-15 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
SEP 28 2015

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Stuffing Box blowout. Pumping unit was shut off and packing was replaced.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*
The well pad surface was affected as well as an approximate 60' X 45' area Southwest of pad where earth berm was washed out by heavy rainfall. A vacuum truck was used to recover 15 bbls of oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: <i>9/29/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-29-15 Phone: 575-602-2188	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/29/15 *2RP-3303*

Patterson, Heather, EMNRD

From: Zack Thomas <zthomas@mewbourne.com>
Sent: Tuesday, September 29, 2015 8:27 AM
To: Patterson, Heather, EMNRD; Tucker, Shelly
Subject: Tamano 11 NC Fed #1H
Attachments: C141- Tamano 11 NC Fed #1H (9-25-15) MOC signed initial.pdf

If there are any questions or concerns please call or email. Thanks



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
PO Box 5270
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com