

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Revi
Submit 2 Co
District O
with

Release Notification and Corrective Action

OPERATOR		Initial Report	Final Report
Name of Company	John H. Hendrix, Corp	Contact	MARVIN BURROWS
Address	P.O. Box 910 Eunice N.M. 88231	Telephone No.	505-394-2649
Facility Name	Amanda Sims BATT.	Facility Type	TANK BATTERY
Surface Owner	Winnie Kennan	Mineral Owner	
			Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	25	22S	37E	66	1990'	S	660'	E
								LEA

Latitude _____ Longitude GPS! N 32° 21m 38.6S
W 103° 6m 37.4S

NATURE OF RELEASE

Type of Release	WATER/OIL	Volume of Release	4.5 BBL	Volume Recovered	3 BBL
Source of Release	WATER TANK	Date and Hour of Occurrence	7am	Date and Hour of Disco	
Was Immediate Notice Given?	Yes <input checked="" type="radio"/> No <input checked="" type="radio"/> Not Required	If YES, To Whom?	1116106		
By Whom?	_____	Date and Hour	_____		
Was a Watercourse Reached?	Yes <input checked="" type="radio"/> No <input checked="" type="radio"/>	If YES, Volume Impacting the Watercourse.	_____		

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Pumper ran water TANK OVER.

Describe Area Affected and Cleanup Action Taken.*

Area approx. 6' wide x 18' Long (E-W).
Picked up LIQUID w/ VAC. TRUCK.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any oil or local laws and/or regulations.

Signature:	<u>Marvin Burrows</u>	ce	Marvin Burrows Production Supt. John H. Hendrix Corp. Eunice, N.M.
ce	of a C-141 r	ce	
docs no		relieve the op	erator of responsi
t	y for compliance	wi	
y	other federal, state, or local laws and/or regulations. <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Signature	

John Hendrix 12024
Facility - APAC 060623 2739

incident - nPAC0606232838
application - pPAC0606232975