


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company ExxonMobil	Contact Toni Collier
Address P.O. Box 4358, Houston, TX 77210	Telephone No. 281-654-1133
Facility Name State ZZ ABO	Facility Type Tank Battery
Surface Owner New Mexico State	Mineral Owner New Mexico State
Lease No. 8054	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	7	17S	35E	2300	North	1950	West	Lea

78' Latitude N 32.51.078 Longitude W 103.29.968

#### NATURE OF RELEASE

Type of Release Oil	Volume of Release 8.95 bbls	Volume Recovered 0
Source of Release Tank	Date and Hour of Occurrence 6/10/05 1PM	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
500 bbl tank block in for oil sales. Centurion Pipeline (Oxy) opened valves to sell tank and their check valve did not hold. Oil backflowed from sales line overflowing tank. Most of the oil stayed on the pad.

Describe Area Affected and Cleanup Action Taken.\*  
Tank was shut in. Centurion will repair their valve.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Laura T. Johnson		Approved by District Supervisor:	
Title: Compliance Supervisor		Approval Date:	Expiration Date:
E-mail Address: Laura.T.Johnson@exxonmobil.com		Conditions of Approval:	
Date: 8/27/05 Phone: 281-654-1130		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

*Exxon Mobil - 7673  
facility - PPAC0606651913*

*incident - nPAC0606652028  
application - pPAC0606652709*