

Well
N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Doyle Hartman	Contact	Don Mashburn
Address	500 N. Main Midland, Texas 79701	Telephone No.	(432) 684-4011
Facility Name	State "H" Tank Battery	Facility Type	Production
Surface Owner	State	Mineral Owner	State of New Mexico
		Lease No.	B-1484

LOCATION OF RELEASE

Unit/Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County	Lea
A	17	22S	36E	330	PNL	660	PBL		

Latitude 32.39979 North Longitude 103.28075 West

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	99 bbls	Volume Recovered	9 bbls
Source of Release	500 bbl Fiberglass Water tank	Date and Hour of Occurrence	July 8, 2003 (Between 9:45 p.m. and 11:45 p.m. MST)	Date and Hour of Discovery	July 8, 2003 11:45 p.m. MST
Was Immediate Notice Given?	☒ Yes ☐ No ☐ Not Required	If YES, To Whom?	Gary Wink		
By Whom?	Don Mashburn	Date and Hour	July 9, 2003 7:05 a.m. (MST)		
Was a Watercourse Reached?	☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

From an Electrical Storm -- Lightning hit the 500 bbl. Fiberglass produced water tank causing an explosion and fire.

Describe Area Affected and Cleanup Action Taken.*

The Bunice Fire Department was called out to extinguish the fire. There was no oil or water to pickup. We are going to contact an Environmental company to check soil samples and cleanup. We plan to replace the 500 bbl water tank with a new 300 bbl fiberglass tank and replace the 2 -300 bbl oil stock tanks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCED rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCED marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCED acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Mashburn</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Mashburn	Approved by District Supervisor	
Title: Engineer	Approval Date:	Expiration Date:
E-mail Address: dhao-11@swbell.net	Conditions of Approval:	Attached ☐
Date: July 11, 2003	Phone: (432) 684-4011	

* Attach Additional Sheets If Necessary

Doyle Hartman - 6473
facility - PAC0607440971

incident - PAC0607441055
application - PAC0607441307