

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 30 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

FAB1527452226 OPERATOR Initial Report Final Report
NAB1527452541

Name of Company: Regency Field Services <i>313040</i>	Contact: Johnnie Bradford
Address: 600 N. Marienfeld Street	Telephone No. (432) 250-5542 (cell) (817) 302-9812 (off)
Facility Name: California C (Pecos River) Pipeline	Facility Type: Pipeline

Surface Owner:	Mineral Owner:	API No.
----------------	----------------	---------

LOCATION OF RELEASE

Unit Letter	Section 02	Township 26 S	Range 31 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	------------	---------------	------------	---------------	------------------	---------------	----------------	-------------

32.297777 Latitude 32 3.892 N *103.006666* Longitude 103.44.984 W

NATURE OF RELEASE

Type of Release: Gas, produced water and condensate	Volume of Release: Gas Unkown Liquid ~ 20 bbls	Volume Recovered: Unknown
Source of Release: Hole in Pipeline	Date and Hour of Occurrence: 09/26/2015 08:00	Date and Hour of Discovery: 09/26/2015 08:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Emergency Number -(575) 370-3186	
By Whom? Johnnie Bradford	Date and Hour: 06/26/2015 12:06 CST	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Watercourse not impacted.

Describe Cause of Problem and Remedial Action Taken.*

A bell hole was dug down to the leak and a clamp affixed to immediately contain the leak. Additional repairs may be needed at which time this C-141 will be updated to reflect the final repairs if needed and required.

Describe Area Affected and Cleanup Action Taken.*

The area affected was largely pasture and the ROW next to the pipeline. A vacuum truck was used to remove all the free liquid from the surface. The ROW was scraped and back dragged to remove any contaminated soil that resulted from the spray of material. Any wet soil was removed and placed on a bermed, plastic area to await further remedial actions. The remainder of the contaminated soil will be removed and the area sampled to confirm cleanup as per OCD guidance. The final report will describe the remedial actions in more detail. Please note the time and volume of material lost/recovered are estimations more accurate estimates will be included with the final report as well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Johnnie Bradford	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Sr. Environmental Specialist	Approval Date: 10/1/15	Expiration Date: N/A
E-mail Address: johnnie.bradford@energytransfer.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/26/2015 Phone: (817) 302-9812	Remediation per O.C.D. Rules & Guidelines	

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/7/15**

2RP-3308

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Jones, Kellie, EMNRD
Sent: Wednesday, September 30, 2015 2:53 PM
To: Bradford, Johnnie
Cc: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: FW: Updated C-141 California C Pipeline - Regency Field Services
Attachments: 09262015-C141CalC-Rev-Ini.pdf

Johnnie,

This site is in District II, Heather or Mike will be able to assist you with this.

Have a great day!

Kellie Jones
Environmental Specialist, District I
Oil Conservation Division, EMNRD
575-393-6161 ext. 111
575-370-3180 (emergency-cell)
E-Mail: kellie.jones@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Bradford, Johnnie [mailto:Johnnie.Bradford@energytransfer.com]
Sent: Wednesday, September 30, 2015 1:21 PM
To: Jones, Kellie, EMNRD; Randal Pair
Subject: Updated C-141 California C Pipeline - Regency Field Services

Good Afternoon Kellie/Randal,

I have attached a revised C-141 that contains the Township and Range as well as the county. Randal a work plan is in the works and will be submitted to you shortly.

If you should have any questions, please let me know.

Johnnie



Johnnie Bradford Energy Transfer Partners – Sr. Environmental Specialist
600 N. Marienfeld Str. Ste. 700 Midland, Texas 79701 | (817) 302-9812/(432) 250-5542

Private and confidential as detailed [here](#). If you cannot access hyperlink, please e-mail sender.