

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1528841728

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production <i>U137</i>	Contact Garry Michael, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-4895
Facility Name Ross Ranch 10 Fed 1 SWD	Facility Type SWD

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29605
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	26S	31E	1980	North	660	East	Eddy

Latitude: 32.059235486

Longitude: -103.75905787

NATURE OF RELEASE

Type of Release Produced Water Spill	Volume of Release 400bbls	Volume Recovered 400bbls
Source of Release Nipple on gun barrel	Date and Hour of Occurrence October 1, 2015 6:34 PM	Date and Hour of Discovery October 1, 2015 6:34 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Kellie Jones, OCD	
By Whom? David Washington, Assistant Production Foreman	Date and Hour Jim Amos, BLM October 1, 2015 12:00 AM Kellie Jones, OCD October 1, 2015 12:05 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
 ARTESIA DISTRICT
 OCT 15 2015
 RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
On October 1, 2015 6:34 PM at the Ross Ranch 10 Fed 1 SWD a 3" threaded nipple corroded on the gun barrel and caused a release of 400bbl produced water into lined containment. The Lease Operator immediately shut in the wells going to the SWD and did a lock out tag out on the gun barrel until repairs could be made.

Describe Area Affected and Cleanup Action Taken.*
All 400bbl of fluid released were contained in lined containment and a vac truck was called to clean up containment. All 400bbls produced water were recovered and the containment was checked for holes with none found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>10/15/15</i>	Expiration Date:
E-mail Address: Sheila.Fisher@dmv.com	Conditions of Approval: <i>FINAC</i>	Attached <input type="checkbox"/>
Date: 10/13/2015 Phone: 575.748.1829		

* Attach Additional Sheets If Necessary

2RP-3337

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Wednesday, October 14, 2015 2:00 PM
To: Jim Amos (jamos@blm.gov); Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Fulks, Brett; Harris, Jacqui
Subject: Ross Ranch 10 Fed 1 SW_ 400bbl PW release_10.1.15
Attachments: Ross Ranch 10 Fed 1 SWD_400bbl PW release_10.1.15_ GIS Image word.docx; Ross Ranch 10 Fed 1 SWD_400bbl PW release_10.1.15_ Initial & Final C-141.doc; Ross Ranch 10 Fed 1 SWD_400bbl PW release_10.1.15_ photo 1 of 3.JPG; Ross Ranch 10 Fed 1 SWD_400bbl PW release_10.1.15_ photo 2 of 3.JPG; Ross Ranch 10 Fed 1 SWD_400bbl PW release_10.1.15_ photo 3 of 3.JPG

Good Morning,

Attached please find the Initial & Final C-141, GIS Image and photos for the 400bbl produced water release into containment at the Ross Ranch 10 Fed 1 SWD.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.