

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1529941728*

**OPERATOR**  Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production <i>6137</i>	<b>Contact</b> Rudy Zuniga
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88220	<b>Telephone No.</b> 575-390-5435
<b>Facility Name</b> Diamond PWU 22-5H	<b>Facility Type</b> Oil

<b>Surface Owner</b> State	<b>Mineral Owner</b> State	<b>API No.</b> 30-015-40822
----------------------------	----------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	19S	29E	725	North	330	West	Eddy

Latitude: N 32°65'14.21"

Longitude: W 104°06'96.26"

**NATURE OF RELEASE**

<b>Type of Release Spill</b> Produced Water and Oil	<b>Volume of Release</b> 6 bbls oil and 4 bbls water	<b>Volume Recovered</b> 3 bbls oil and 2 bbls produced water
<b>Source of Release</b> Frac Tank over flowed	<b>Date and Hour of Occurrence</b> 10/22/2015 @ 11:20 AM	<b>Date and Hour of Discovery</b> 10/22/2015 @ 11:20 AM
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Mike Bratcher OCD	
<b>By Whom?</b> Jesse Armendariz, Assistant Production Foreman	<b>Date and Hour</b> 10.22.2015 @ 11:45 am	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**NM OIL CONSERVATION**  
 ARTESIA DISTRICT  
 OCT 23 2015  
 RECEIVED

**If a Watercourse was Impacted, Describe Fully.\***  
N/A

**Describe Cause of Problem and Remedial Action Taken.\***  
Frac tank burped causing a 6 bbl oil and 4 bbl produced water release. Well was immediately shut in to prevent further release.

**Describe Area Affected and Cleanup Action Taken.\***  
6 bbls oil and 4 bbls produced water was released on the North, North West side of the facility. 3 bbls oil and 2 bbls produced water was recovered via vacuum truck. The affected area was a 100 x 50 and all released fluid remained on location. Environmental Agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
<b>Title:</b> Field Admin Support	Approval Date: <i>10/26/15</i>	Expiration Date: <i>N/A</i>
<b>E-mail Address:</b> corina.moya@dvn.com	Conditions of Approval:	
<b>Date:</b> 10/22/2015 <b>Phone:</b> 575.746.5559	Attached <input type="checkbox"/>	

**Remediation per O.C.D. Rules & Guidelines**  
**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: 11/24/15** *2RP-3352*

\* Attach Additional Sheets If Necessary

## **Patterson, Heather, EMNRD**

---

**From:** Moya, Corina <Corina.Moya@dvn.com>  
**Sent:** Friday, October 23, 2015 1:57 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** Diamond PWU 22-5H Incident  
**Attachments:** Diamond PWU 22-5H 10 bbl pw and oi spill 10.22.15.pdf.doc; Diamond PWU 22-5H 10 bbl pw and oi spill 10.22.15.pdf.doc; Diamond PWU 22-5H 10 bbl pw and oi spill 10.22.15.pdf

Good afternoon,

Please see attached C-141, pic, and GIS Mapping for the incident at the Diamond PWU 22-5H from 10.22.15.

Thank you,

**Corina Moya**  
Field Admin Support  
Production  
B Schedule

**Devon Energy Corporation**  
PO Box 250  
Artesia, NM 88211  
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.