

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1432841543

Release Notification and Corrective Action

NAB1432850987

OPERATOR

Initial Report Final Report

Name of Company	Enterprise Field Services LLC 1000347	Contact	Dina Babinski
	PO Box 4324, Houston, TX 77252	Telephone No.	210-528-3824
Facility Name	Pipeline ROW, 30137 Gathering Lateral	Facility Type:	Gas Gathering Pipeline
Surface Owner	State of New Mexico	Mineral Owner	NA - Pipeline
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SWSE	13	19S	28E	60	South	144	West	Eddy

Latitude: N 32.653889 Longitude: W -104.129961

NATURE OF RELEASE

Type of Release	Natural Gas, Pipeline Liquids	Volume of Release:	1647 MCF, 5 BBL Liquids	Volume Recovered:	N/A
Source of Release	Pipeline Leak.	Date and Hour of Occurrence	09/29/2014 @ 08:40 MDT	Date and Hour of Discovery	09/29/2014 @ 08:40 MDT
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, District 2		
By Whom?	Osman De Leon	Date and Hour	09/29/2014 @ 10:46 MDT		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	NM OIL CONSERVATION ARTESIA DISTRICT		

If a Watercourse was Impacted, Describe Fully.*
OCT 17 2014

Describe Cause of Problem and Remedial Action Taken.*
Pipeline leak was detected by pumper driving by. Pipeline segment was clamped and blown down, and leaking portion was repaired.
RECEIVED

Describe Area Affected and Cleanup Action Taken.*
Liquid spill occurred within pipeline ROW. Cleanup activities are currently being performed and additional sampling has been requested to confirm cleanup is satisfactory.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Jon E. Fields	Approved by District Supervisor:	
Title:	Director, Field Environmental	Approval Date:	11/4/14
E-mail Address:	jefields@eprod.com	Expiration Date:	N/A
Date:	10/13/2014	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	713-381-6684	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 12/4/14	

* Attach Additional Sheets If Necessary

2RP-2623



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

October 13, 2014

NM OIL CONSERVATION
ARTESIA DISTRICT

OCT 17 2014

Return Receipt Requested
7014 1200 0001 0918 2109

RECEIVED

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Release on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher,

Enclosed, please find the required initial C-141 Form report for the unplanned release on our 30137 Line in Eddy County on September 29, 2014.

This report is sent pursuant to NMAC 19.15.29 and as follow-up to verbal notifications made to your office over the phone by Osman De Leon on September 29th, 2014 at 10:46 AM CDT. Cleanup activities are currently underway, and a final C-141 form will be submitted when soil sampling results demonstrate that cleanup of the affected area is complete.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor at 210-528-3824, or me at 713-381-6684.

Yours truly,

Jon E. Fields
Director, Field Environmental

/bjm
Attachment