

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

NOV 12 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1532031688

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO SWD #104	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-25864
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	26S	28E	1980'	North	1980'	West	Eddy

Latitude 32.0588913 Longitude -104.0774612

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 60 bbls PW	Volume Recovered: 58 bbls PW
Source of Release: Over ran Tank	Date and Hour of Occurrence: 11/4/2015 4:40 am	Date and Hour of Discovery: 11/4/2015 4:40 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Thu 11/5/2015 4:28 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused when a high volume alarm failed and the tank ran over. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a lined facility. All fluid was able to be recovered. The facility was cleaned and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>11/10/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: 11/12/15 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-3394

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Thursday, November 12, 2015 5:11 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (C-141 Initial-Final) SRO SWD #104 (30-015-25864)
Attachments: 11-4-2015 SRO SWD #104 (TB) Initial-Final.pdf

Mr. Bratcher,

Attached is a C-141 Initial-Final for your consideration. Please feel free to contact me if you have any questions or concerns.

Thank you,

Amanda Trujillo Davis

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

1401 Commerce Drive
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Amanda Trujillo Davis
Sent: Thursday, November 05, 2015 4:28 PM
To: Heather Patterson; Mike.Bratcher@state.nm.us
Subject: (Notification) SRO SWD #104 (30-015-25864)

Mr. Bratcher,

COG Operating LLC is reporting a release on the SRO SWD #104 (30-015-25864)
Unit F Section 10, Township 26S Range 28E
The release occurred at 4:00 am on 11/4/2015.
Released: 1 bbls Oil ; 60 bbls Produced Water
Recovered: 1 bbls Oil ; 58 bbls Produced Water

The release was caused when a high volume alarm failed and the tank ran over. This release occurred within a lined facility. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2407 Pecos Ave.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Thursday, November 05, 2015 4:28 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification) SRO SWD #104 (30-015-25864)

Mr. Bratcher,

COG Operating LLC is reporting a release on the SRO SWD #104 (30-015-25864)
Unit F Section 10, Township 26S Range 28E
The release occurred at 4:00 am on 11/4/2015.
Released: 1 bbls Oil ; 60 bbls Produced Water
Recovered: 1 bbls Oil ; 58 bbls Produced Water

The release was caused when a high volume alarm failed and the tank ran over. This release occurred within a lined facility. The area is being evaluated and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.