

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DEC 08 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1534451906*

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Devon Energy Production Company</b> <i>6137</i>		Contact <b>Garry Michael, Production Foreman</b>
Address <b>6488 Seven Rivers Hwy Artesia, NM 88210</b>		Telephone No. <b>575-513-4895</b>
Facility Name <b>Cotton Draw Unit 135H</b>		Facility Type <b>Oil</b>
Surface Owner <b>Federal</b>	Mineral Owner <b>State</b>	API No <b>30-015-38533</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	25S	31E	200	South	1600	West	Eddy

Latitude: N 32°15'27.67"

Longitude: W -103°75'20.49"

**NATURE OF RELEASE**

Type of Release Spill <b>Oil</b>	Volume of Release <b>110bbls</b>	Volume Recovered <b>100bbls</b>
Source of Release <b>Pump housing on LACT unit split in two</b>	Date and Hour of Occurrence <b>November 30, 2015 10:17 AM</b>	Date and Hour of Discovery <b>November 30, 2015 10:17 AM</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Kellie Jones, OCD Jim Amos, BLM</b>	
By Whom? <b>Matt Nettles, Assistant Production Foreman</b>	Date and Hour <b>Kellie Jones, OCD December 1, 2015 10:15 AM Jim Amos, BLM December 1, 2015 10:17 AM</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Pump housing on the LACT unit had split in two causing the oil from oil tanks to spill over. This caused a 110bbl oil release. The valve on the oil tank was shut in to prevent any further release. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

110bbls of oil was released on the North, North West side of the facility. 100bbls of oil was recovered via vacuum truck. The affected area was 100'x200'. All released fluid remained on location. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Signed By <i>Mike Brumley</i> Approved by Environmental Specialist:	
Title: <b>Field Admin Support</b>	Approval Date: <b>12/10/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>corina.moya@dvn.com</b>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: <b>12.3.2015</b> Phone: <b>575.746.5587</b>	<b>LATER THAN: <u>11516</u></b>	

\* Attach Additional Sheets If Necessary

*2RP-3437*

## Bratcher, Mike, EMNRD

---

**From:** Fisher, Sheila <Sheila.Fisher@dvn.com>  
**Sent:** Tuesday, December 08, 2015 3:18 PM  
**To:** Jim Amos (jamos@blm.gov); Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Fulks, Brett; Scrogum, Sandy; Nettles, Matt; Michael, Garry  
**Subject:** Cotton Draw Unit 135H\_110bbl oil release\_11.30.15  
**Attachments:** Cotton Draw Unit 135H\_110bbl oil release\_Initial C-141\_11.30.15.doc; Cotton Draw Unit 135H\_110bbl oil release\_GIS Image\_11.30.15.pdf; Cotton Draw Unit 135H\_110bbl oil release\_picture 1 of 1\_11.30.15.jpg

Good Morning,

Attached please find the Initial C-141, GIS Image and photo for the 110bbl oil release at the Cotton Draw Unit 135H on 11.30.15.

If you have any questions please feel free to contact me.

Thank you,

*Sheila Fisher*  
Field Admin Support  
Production  
A-Schedule

**Devon Energy Corporation**  
PO Box 250  
Artesia, NM 88211  
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.