

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 08 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1534452923

Name of Company Devon Energy Production 10137		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Contact Ruben Garcia Assistant Production Foreman		
Facility Name Todd 36 State 1		Telephone No. 575.748.5209		
		Facility Type SWD		
Surface Owner State	Mineral Owner Federal & State	API No. 30-015-20341		

LOCATION OF RELEASE

Unit Letter I	Section 26	Township 23S	Range 31E	Feet from the 990	North/South Line FSL	Feet from the 1980	East/West Line FEL	County Eddy
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.271810 Longitude: -103.744224

NATURE OF RELEASE

Type of Release Spill Produced water	Volume of Release 1160 BBL	Volume Recovered 30 BBL
Source of Release Water line leak	Date and Hour of Occurrence 12/03/15 at 3:45 pm	Date and Hour of Discovery 12/03/15 at 3:45 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM Jim Amos OCD Mike Bratcher	
By Whom? Ruben Garcia Production Assistant Foreman	Date and Hour 12/04/15 11:23 BLM 12/04/15 11:26 OCD	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused a water line leak coming from the Todd 26 SWD going to the Todd 36 State 1. Shut valve at the Todd 26 SWD and valve at the Todd 36 State 1. Crew is currently working on repairing line.

Describe Area Affected and Cleanup Action Taken.*

1160 BBL of produced water was released and 30 BBL recovered by vacuum truck in a 21,681 square feet area. It was all on pasture, on the north side of lease road leading to the Todd 26 Fed 7. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 12/10/15	Expiration Date: N/A
E-mail Address: Jeanette.barron@dmv.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 12/08/15 Phone: 575.748.1813	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/15/16	

* Attach Additional Sheets If Necessary

2RP-3458

Bratcher, Mike, EMNRD

From: Barron, Jeanette <Jeanette.Barron@dvn.com>
Sent: Tuesday, December 08, 2015 2:12 PM
To: Amos, James; Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Garcia, Ruben; Aguilar, Leonard; Fulks, Brett
Subject: C-141 Todd 36 state 1 SWD
Attachments: Todd 36 st 1 swd pic 8 of 11.JPG; Todd 36 st 1 swd pic 9 of 11.JPG; Todd 36 st 1 swd pic 10 of 11.JPG; Todd 36 st 1 swd pic 11 of 11.JPG; Todd 36 state 1 12.03.15.pdf; C-141 Todd 36 State 1 SWD 12.03.15.doc; Todd 36 st 1 swd pic 1 of 11.JPG; Todd 36 st 1 swd pic 2 of 11.JPG; Todd 36 st 1 swd pic 3 of 11.JPG; Todd 36 st 1 swd pic 4 of 11.JPG; Todd 36 st 1 swd pic 5 of 11.JPG; Todd 36 st 1 swd pic 6 of 11.JPG; Todd 36 st 1 swd pic 7 of 11.JPG

Please see attached, should you have any questions or concerns please contact Assistant Foreman Ruben Garcia or EHS representative Brett Fulks.

Thanks,

Jeanette Barron

Field Admin Support-Production

Devon Energy Corporation

P.O. Box 250

Artesia, NM 88211

575 748 1813 Direct

jeanette.barron@dvn.com

devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.