

DEC 10 2015

Form C-141  
Revised October 10, 2003

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

NAB1534840797

277558 OPERATOR

Initial Report  Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-623-8424
Facility Name: WEST REDLAKE WATER STATION #1	Facility Type: Water Station

Surface Owner :	Mineral Owner:	Lease No.
-----------------	----------------	-----------

API# 30-015-28443

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
B	7	18S	27E					

Latitude 32.768991 N Longitude -104.314224 W

**NATURE OF RELEASE**

Type of Release : Produced Water	Volume of Release : 190 bbls	Volume Recovered: 170 bbls
Source of Release : Flow line leak	Date and Hour of Occurrence: 11/27/15 10:00 am	Date and Hour of Discovery: 11/27/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher	
By Whom? Kimberly Wilson	Date and Hour: 11/27/15 @ 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  A flow line ruptured causing a release of 190 barrels of produced water to be released within the earthen berms of the secondary containment. The release didn't breach the berm. The line was isolated, shut in and repaired. A vac truck was immediately called to location and recovered 170 barrels of fluid. Talon mobilized personnel to the location for initial site assessment and soil sampling activities to generate a work plan.

Describe Area Affected and Cleanup Action Taken.\* All fluids were contained with earthen berms.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: <u>Michael Barrett</u>	Signed By: <u>Mike Bratcher</u>	
Printed Name: Michael Barrett	Approved by District Supervisor:	
Title: Production Supervisor	Approval Date: <u>12/14/15</u>	Expiration Date: <u>NIA</u>
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	
Date: <u>12/10/2015</u> Phone: 575-623-8424	LATER THAN: <u>1/15/16</u>	

\* Attach Additional Sheets If Necessary

2RD. 3445

## Bratcher, Mike, EMNRD

---

**From:** Kimberly M. Wilson <[kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)>  
**Sent:** Thursday, December 10, 2015 3:00 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Cc:** Michael Barrett; David Adkins  
**Subject:** WEST REDLAKE WATER STATION #1 initial C-141  
**Attachments:** WRLU Water Station 1 C-141 (Signed).pdf

Hello Mike and Heather,

Attached is the initial C-141 for the above referenced release.

Respectfully submitted,

Kimberly M. Wilson  
Project Manager  
TALON/LPE  
408 W. Texas  
Artesia, NM 88210

Direct: 575-616-4023

Cell: 575-602-3826

Email: [kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist

Staples Foundation for Learning Hall of Fame Recipient: 2010

ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006

Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007