

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1535131213*

*6037*

OPERATOR

Initial Report  Final Report

Name of Company <b>Devon Energy Production Company</b>		Contact <b>Rudy Zuniga Production Foreman</b>	
Address <b>6488 Seven Rivers Hwy Artesia, NM 88210</b>		Telephone No. <b>575-390-5435</b>	
Facility Name <b>Peridot 13 State 3H</b>		Facility Type <b>Oil</b>	
Surface Owner State	Mineral Owner State	API No <b>30-015-40778</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	12	19S	29E	1475	North	1245	East	Eddy

Latitude: N 32°67'78.95"

Longitude: W -104°02'38.22"

*32.6782*

**NATURE OF RELEASE**

*104.02374*

Type of Release Spill <b>Produced water and oil</b>	Volume of Release <b>1 bbl oil and 5 bbls produced water</b>	Volume Recovered <b>1 bbl oil and 2 bbls produced water</b>
Source of Release <b>1' tubing</b>	Date and Hour of Occurrence <b>12.11.15 @ 12:00 pm</b>	Date and Hour of Discovery <b>12.11.15 @ 12:00 pm</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Heather @ OCD</b>	
By Whom? <b>Jesse Armendariz Assistant Production Foreman</b>	Date and Hour <b>12.11.15 @ 12:55 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <b>N/A</b>	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
*DEC 16 2015*  
**RECEIVED**

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Gauging on 1' tubing blew out causing a 6 bbl oil and produced water release. Well was shut in to prevent further release. The gauge was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
1 bbl oil and 5 bbl produced water was released on the North, Northwest of the facility. 1 bbl oil and 2 bbl produced water was recovered via vac truck. The affected area was 25"x35". All released fluid remained on the location. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>Field Admin Support</b>	Approval Date: <i>12/17/15</i>	Expiration Date: <i>NA</i>
E-mail Address: <b>corina.moya@dvn.com</b>	Conditions of Approval:	
Date: <b>12.14.2015</b> Phone: <b>575.746.5559</b>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: <i>1/17/16</i></b>	

Attached

\* Attach Additional Sheets If Necessary

*22P-3456*

**Patterson, Heather, EMNRD**

---

**From:** Moya, Corina <Corina.Moya@dvn.com>  
**Sent:** Wednesday, December 16, 2015 10:52 AM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** Peridot 13 State 3H 6 bbl oil and produced water spill  
**Attachments:** Peridot 13 State 3H 6 bbl water and oil spill 12.11.15 pic 1 of 3.jpg; Peridot 13 State 3H 6 bbl water and oil spill 12.11.15 pic 2 of 3.jpg; Peridot 13 State 3H 6 bbl water and oil spill 12.11.15 pic 3 of 3.jpg; Peridot 13 State 3H 6 bbl water and oil spill 12.11.15 C-141 Initial.doc; Peridot 13 State 3H 6 bbl water and oil spill 12.11.15 GIS Mapping.pdf

**Categories:** printed

Good morning,  
Please see attached information for the Peridot 13 State 3H spill on 12.11.2015

Thank you,

**Corina Moya**  
Field Admin Support  
Production  
B Schedule

**Devon Energy Corporation**  
PO Box 250  
Artesia, NM 88211  
575 746 5559



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.