

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

DEC 22 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535832134

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU 29 SWD @ JRU 19 Battery (JRU 19 Battery API 30-015-27357)	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner: Unknown	API No. 30-015-27735
----------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	36	22S	30E	1980	South	1980	East	Eddy

Latitude 32.346632° Longitude -103.832532°

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 13 bbls	Volume Recovered: 10 bbls
Source of Release: Flow Line	Date and Hour of Occurrence: Date/time unknown	Date and Hour of Discovery: 12/14/2015 2 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD)	
By Whom? Amy Ruth	Date and Hour: 12/14/2015 4:53 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A hole developed due to corrosion in the flow line transferring skim oil from the JRU 29 SWD tank to the JRU 19 Battery. The line was clamped and repaired.		
Describe Area Affected and Cleanup Action Taken.* The leak affected 408 ft ² of pasture and 45 ft ² of well pad and standing fluids were recovered from the pasture.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Amy C. Ruth</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Amy C. Ruth	Approval Date: 12/23/15	Expiration Date: N/A
Title: Remediation Specialist	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
E-mail Address: ACRuth@basspet.com	Attached <input type="checkbox"/>	
Date: 12/22/2015 Phone: 432-661-0571	REMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 1/29/16 *2RD3466*