

NM OIL CONSERVATION
ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

JAN 18 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
concordance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

NAB1601536561 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 008H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: API No. 3001539508

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/ <u>South Line</u>	Feet from the	East/ <u>West Line</u>	County
N	14	25S	30	300		1980		Eddy

Latitude: 32.13089 Longitude: 103.84192

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 barrels	Volume Recovered: 6 barrels
Source of Release: Pinhole in SWD Riser	Date and Hour of Occurrence 1-8-2016 @ 9:00am	Date and Hour of Discovery 1-8-2016 @ 9:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A pinhole developed on SWD riser tie in to main line due to internal corrosion. A vacuum truck was called to location and was able to recover 6 barrels of produced water from the ground surface.		
Describe Area Affected and Cleanup Action Taken.* The release occurred on the SWD riser at the tie in point of the main SWD line, the riser is located on the east side of Buck Jackson on the ROW. A vacuum truck was called to the location and was able to recover 6 barrels of produced water.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>1/15/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: <i>1-12-2016</i> Phone: 432-214-3704	Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 1/18/16

2RP-3495

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, January 12, 2016 9:34 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV BS 008H
Attachments: Initial C-141 PLU CVX JV BS 008H.pdf

All,

Please find the attached initial C-141 for the spill that occurred at the PLU CVX JV BS 008H. If you have any questions please let me know. Thank you

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com