

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JAN 12 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1601540259

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: BOPCO, L.P. <i>260737</i>		Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 575-887-7329	
Facility Name: PLU CVX JV BS 028H		Facility Type: Exploration and Production	
Surface Owner: Federal		Mineral Owner: Federal	API No. 3001542393

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	24S	30E	590		1060		Eddy

Latitude: 32.20902 Longitude: 103.84621

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 14 barrels	Volume Recovered: 10 barrels
Source of Release: Stuffing Box	Date and Hour of Occurrence 1-11-2016 @ 8:00am	Date and Hour of Discovery 1-11-2016 @ 8:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
BOPCO pumper reported that the packing in the stuffing box failed. A vacuum truck was called to the location and was able to recover 10 barrels of oil from around the wellhead.		
Describe Area Affected and Cleanup Action Taken.*		
The majority of the fluid collected around the wellhead, a vacuum truck was called to the location and was able to recover 10 barrels of oil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCID rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCID marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCID acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <i>Mike Brumby</i> Approved by Environmental Specialist	
Title: Assistant Remediation Foreman	Approval Date: <i>1/15/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	
Date: <i>1-12-2016</i> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: *1/15/16* *2RP-3496*

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Tuesday, January 12, 2016 10:35 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Amos, James
Cc: Blevins, Bradley
Subject: Initial C-141 PLU CVX JV BS 028H
Attachments: Initial C-141 PLU CVX JV BS 028H.pdf

All,

Please find the attached initial C-141 for the release that occurred at the PLU CVX JV BS 028H. If you have any questions please let me know. Thank you

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com