

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JAN 18 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1601927284

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Burnett Oil Co., Inc. <i>3080</i>	Contact	Leslie Garvis
Address	Burnett Plaza - Suite 1500, 801 Cherry Street-Unit 9, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Jackson A 2	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-37494

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	17S	30E	1115	South	2210	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	27 bbls	Volume Recovered	25 bbls
Source of Release	Poly Pipe	Date and Hour of Occurrence		Date and Hour of Discovery	1/12/2016 1000
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM - S. Tucker, OCD - H. Patterson		
By Whom?	Leslie Garvis	Date and Hour	01/12/2016 1500		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Leak in flowline. Contained within lined berm. Pipeline will be repaired and returned to service					
Describe Area Affected and Cleanup Action Taken.* Area affected is approx 20' x30' inside the lined berm. Vacuum truck was used to collect the standing water. Once the area is dry, we will assess the impacted area and see if any material needs to be removed.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>Leslie Garvis</i>		OIL CONSERVATION DIVISION			
Printed Name: Leslie Garvis		Approved by Environmental Specialist: <i>[Signature]</i>			
Title: Regulatory Coordinator		Approval Date: 1/18/16		Expiration Date: N/A	
E-mail Address: lgarvis@burnettoil.com		Conditions of Approval:			
Date: 1/18/16		Phone: 817-583-8730		Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 1/18/16

2RP-3499

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Leslie Garvis <lgarvis@burnettoil.com>
Sent: Monday, January 18, 2016 12:17 PM
To: stucker@blm.gov; Patterson, Heather, EMNRD
Cc: Walter Glasgow; Brady Sullivan; Trey Krampf; Johnny Titsworth; Kyle Adams; Charlie Smitherman
Subject: Initial C-141 for Release at the Jackson A 2 Tank Battery / API# 30-015-37494
Attachments: 2015.01.18 Initial C-141 Smtd.pdf

Shelly/Heather,

Attached you will find the Initial C-141 for the 1/11/16 release at the Jackson A 2 tank battery.

Please let me know if you have any questions or need any additional information.

Thank you.

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL CO., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881
DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

From: Leslie Garvis
Sent: Tuesday, January 12, 2016 3:34 PM
To: stucker@blm.gov; Heather.Patterson@state.nm.us
Cc: Walter Glasgow; Brady Sullivan; Trey Krampf; Johnny Titsworth; Kyle Adams; Charlie Smitherman
Subject: Release at the Jackson A 2 Tank Battery / API# 30-015-04129

Shelly/Heather,

We had a release at the Jackson A 2 Tank Battery yesterday of produced water. It was approximately 27 bbls and 25 bbls were recovered. All was contained within the lined berm.

C-141 to follow.

LESLIE M. GARVIS
REGULATORY COORDINATOR

BURNETT OIL CO., INC.
BURNETT PLAZA-SUITE 1500
801 CHERRY STREET - UNIT #9
FORT WORTH, TX 76102-6881

DIRECT LINE: 817.583.8730
MOBILE: 713.819.4371
FAX: (817) 332-2438
EMAIL: LGARVIS@BURNETTOIL.COM

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.