

NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

JAN 14 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Release Notification and Corrective Action

NAB 1601927715 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260731</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #066	Facility Type: Exploration and Production

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-31065
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 36	Township 22S	Range 30E	Feet from the 660	North/South Line South	Feet from the 990	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.34313° Longitude -103.83973°

NATURE OF RELEASE

Type of Release Crude Oil/Produced Water	Volume of Release 6 bbls Oil, 1.5 bbls PW	Volume Recovered 0 bbls
Source of Release Well head	Date and Hour of Occurrence 1/12/2016 time unknown	Date and Hour of Discovery 1/12/2016 at 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The well head stuffing box packing failed and fluid sprayed onto the well pad. E-Pot unit on the wellhead shut the pumping unit down. Well head and bull pen were washed and the packing was replaced.		
Describe Area Affected and Cleanup Action Taken.* The leak affected 5,470 ft ² of well pad north of the well head. No standing fluids to recover.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Supervisor	Approval Date: <i>1/15/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1/14/2016 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *1/15/16*

2RP-3500

Bratcher, Mike, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Thursday, January 14, 2016 3:42 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: James Ranch Unit #066 release 1-12-16
Attachments: Initial C-141 JRU 66 1-12-16.pdf; DSCF3975.JPG

Hi everyone, hope your holidays were good ☺ Here is my first initial C-141 for the year. Stuffing box packing blew out and location was sprayed with fluids. Please call me with any questions and hope to get to your office to visit you soon.



Amy C. Ruth

BOPCO, L.P.

EH&S Remediation Specialist

522 W. Mermod, Suite 704

Carlsbad, NM 88220

Office: (575)887-7329

Fax: (575)887-7473

Cell: (432)661-0571