

76 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1602551825** OPERATOR  Initial Report  Final Report

Name of Company <b>BOPCO, L.P.</b> <b>260737</b>	Contact	
Address <b>P.O. Box 2760, Midland Texas 79702</b>	Telephone No. <b>432-683-2277</b>	
Facility Name <b>James Ranch Unit 190H</b>	Facility Type: <b>Drilling Location</b>	
Surface Owner	Mineral Owner	API No. <b>30-015-42145</b>

**LOCATION OF RELEASE**

Unit Letter <b>A</b>	Section <b>36</b>	Township <b>22S</b>	Range <b>30E</b>	Feet from the <b>630</b>	North/South Line <b>North</b>	Feet from the <b>370</b>	East/West Line <b>EAST</b>	County <b>EDDY</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude 32.353967 Longitude -103.858761

**NATURE OF RELEASE**

Type of Release <b>Contaminated soil</b>	Volume of Release	Volume Recovered
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
Describe Area Affected and Cleanup Action Taken.* 12 yards of contaminated soil following drilling location cleanup was hauled to CRI 5/01/2014.		

**RECEIVED**  
 MAY 21 2014  
 NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <b>TASHA SPORT</b>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Tasha Sport</b>	Approved by Environmental Specialist <b>NMOCD</b>	
Title: <b>Regulatory Compliance Manager</b>	Approval Date: <b>1/25/16</b>	Expiration Date: <b>NIA</b>
E-mail Address: <b>Tasha@sportenvironmental.com</b>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: <b>5/13/2014</b> Phone: <b>432-683-1100</b>		

\* Attach Additional Sheets If Necessary

**2RP-3512**




**SPORT ENVIRONMENTAL SERVICES, PLLC**

**502 N. Big Spring Street, Midland, Texas 79701  
Business: 432.683.1100 Fax: 888.500.0622**

May 13, 2014

Mr. Mike Bratcher  
State of New Mexico  
Oil Conservation Division  
811 S. First Street  
Artesia, NM 88210



Re: **Closed-Loop System Closure Report  
BOPCO, L.P., James Ranch Unit #190H  
Section 36, T-22-S, R-30-E  
Eddy County, New Mexico**

Dear Mr. Bratcher,

On behalf of BOPCO, L.P., Sport Environmental Services is providing the enclosed NMOCD Release Notification and Corrective Action, Form C-141 for BOPCO, L.P.'s James Ranch Unit #190H location.

Following casement of drilling operations, restoration of the impacted area involved, blading and smoothing out the location. Site closure consisted of removing visual signs of contaminated soil and restoring the impacted area with reclaimed caliche. Approximately 12 cubic yards of visually impacted soil was excavated and disposed of offsite at the NMOCD permitted and approved facility, Lea Land, Inc Landfill. (Permit #WM-1-035). Caliche from the edge of the location was used as backfill.

If you have any questions or comments with regard to this matter, please contact me at my office (432.683.1100). I would be more than happy to review this closure report with you.

Sincerely,

A handwritten signature in black ink that reads "TASHA SPORT".

Tasha Sport  
Regulatory Compliance Manager

*Enclosures: NMOCD Form C-141 (Release Notification and Corrective Action)*