

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 25 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1602635193

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company <i>6137</i>		Contact Wendell Barrett – Assistant Construction Foreman	
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 505-529-1843	
Facility Name ORE IDA 14 Federal 1		Facility Type Oil Well	
Surface Owner Federal		Mineral Owner Federal	
		API No 3001528956	

LOCATION OF RELEASE

Unit Letter D	Section 14	Township 24S	Range 29E	Feet from the 660	North/South Line N	Feet from the 480	East/West Line W	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	------------------------------	-----------------------------	----------------------------	-----------------------

Latitude: 32.22289

Longitude: 103.961726

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 BBLs	Volume Recovered 2BBLs
Source of Release Polyline - Flowline	Date and Hour of Occurrence 1/21/2016 9:30 A.M.	Date and Hour of Discovery 1/21/2016 9:30 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM: Jim Amos OCD: Mike Bratcher	
By Whom? Wendell Barrett – Assistant Construction Foreman	Date and Hour BLM: January 22, 2016 2:25 PM OCD: January 22, 2016 2:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Surface polyline/flowline was struck resulting in release. Line was shut off to prevent further release. The line was uncovered and fused back together.

Describe Area Affected and Cleanup Action Taken.*
Approximately 5 BBLs of Produced water was released from surface polyline/flowline on the lease road on the east side of ORE IDA 14 Federal 1. Approximate size of the affected area is 10' x 10'. 2 BBLs produced water was recovered by Vacuum Truck. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Nicole Wedman</i>	OIL CONSERVATION DIVISION	
Printed Name: Nicole Wedman	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: nicole.wedman@dvn.com	Approval Date: <i>1/26/16</i>	Expiration Date: <i>N/A</i>
Date: 1/25/2016 Phone: 575.748.1820	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *2/2/16*

* Attach Additional Sheets If Necessary

2RP-5515

Bratcher, Mike, EMNRD

From: Wedman, Nicole <Nicole.Wedman@dvn.com>
Sent: Monday, January 25, 2016 3:19 PM
To: jamos@blm.gov; stucker@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; agroves@slo.state.nm.us
Cc: Scrogum, Sandy; DeLaRosa, Dana
Subject: ORE IDA 14 Fed 1 5 BBLs PW 1.21.16
Attachments: ORE IDA 14 Fed 1 5 BBLs PW 1.21.16 Initial C-141.doc; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 GIS Image.pdf; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 1 of 6.jpg; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 2 of 6.jpg; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 3 of 6.jpg; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 4 of 6.jpg; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 5 of 6.jpg; ORE IDA 14 Fed 1_5 BBLs PW_1.21.16 Pic 6 of 6.jpg

Good Afternoon,

Attached is the initial C-141 pictures and GIS image for the 5 BBLs produced water release that occurred on the lease road near the ORE IDA 14 Federal 1 on January 21, 2016. The red dot on the GIS image represents the approximate origin of the release.

Thank you,

Nicole Wedman
Field Admin Support - Construction



Devon Energy Production
6488 Seven Rivers Hwy
Artesia, NM 88210
575-748-1820
nicole.wedman@dvn.com

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.