

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

JAN 25 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

*NAB 160263497*

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 028H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001542393
------------------------	------------------------	--------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	24S	30E	590		1060		Eddy

Latitude: 32.20902 Longitude: 103.84621

**NATURE OF RELEASE**

Type of Release: Crude Oil/ Produced Water	Volume of Release: 8 barrels oil, 10 barrels PW	Volume Recovered: 5 barrels oil, 10 barrels PW
Source of Release: Stuffing Box	Date and Hour of Occurrence: 1-21-16 @ 8:00am	Date and Hour of Discovery: 1-21-16 @ 8:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A stuffing box release occurred in the same area as spill dated 1-11-16. A vacuum truck was called to the location and recovered 15 barrels of oil and produced water.

Describe Area Affected and Cleanup Action Taken.\*  
A stuffing box release occurred in the same area as spill dated 1-11-16. A vacuum truck was called to the location and recovered 15 barrels of oil and produced water. An environmental response crew was scheduled to be on location the same day and was able to get the release area scraped up in a timely manner and sampled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Signed By <i>Mike Blevins</i> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <i>1/26/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com <i>1-25-16</i>	Conditions of Approval: <input type="checkbox"/> <b>Remediation per O.G.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO** *2127116*  
**LATER THAN:** *2/2/16* *2RP-3516*

## Bratcher, Mike, EMNRD

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Monday, January 25, 2016 3:48 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Blevins, Bradley  
**Subject:** PLU CVX JV BS 028H 1-21-16  
**Attachments:** Initial C-141 PLU CVX JV BS 028H 1-21-16.pdf

Mike/ Heather

Please find the attached initial C-141 for a secondary release that occurred at the BS 028H location. The release covered the same area as release reported on 1-11-16. A environmental response crew was scheduled to be on location that afternoon to address previous spill and was able to scrape and sample the site. If you have any questions please let me know. Thanks,

Brad Blevins  
Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
bblevins@basspet.com