

FEB 02 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
RECEIVED
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB110040310171

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: COLT STATE SWD #004	Facility Type: SWD
Surface Owner: State	Mineral Owner:
API No. 30-015-41401	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	5	25D	28E	1066'	North	850	West	Eddy

Latitude 32.1636543 Longitude -104.1154556

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 2 bbls Oil 325 bbls PW	Volume Recovered: 2 bbls Oil 325 bbls PW
Source of Release: Tank Overflow	Date and Hour of Occurrence: 1/16/2016 12:00 pm	Date and Hour of Discovery: 1/16/2016 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: Mon 1/18/2016 11:41 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused when a high volume alarm malfunctioned, resulting in the tank overflowing. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a lined facility. All fluid was able to be recovered, the facility cleaned, repaired, and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert McNeill</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert McNeill		Signed By: <i>Michelle Hernandez</i> Approved by Environmental Specialist:	
Title: Environmental Manager		Approval Date: 2/9/16	Expiration Date: N/A
E-mail Address: rmcneill@concho.com		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: January 30, 2016 Phone: 432-230-0077			

* Attach Additional Sheets if Necessary

2RP-3541

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Monday, February 01, 2016 2:09 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (C-141 Initial-Final) COLT STATE SWD #004 (30-015-41401)
Attachments: 1-16-2016 Colt State SWD #4 (TB) Initial-Final.pdf

Mr. Bratcher,

Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo Davis

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

1401 Commerce Drive
Carlsbad, NM 88220



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Amanda Trujillo Davis
Sent: Monday, January 18, 2016 11:41 AM
To: Heather Patterson; Mike.Bratcher@state.nm.us
Subject: (Notification) COLT STATE SWD #004 (30-015-41401)

Mr. Bratcher,

COG Operating LLC is reporting a release on the COLT STATE SWD #004 (30-015-41401)
Unit D Section 5 Township 25S Range 28E
The release occurred at 12:00 pm on 1/16/2015.
Released: 325 bbls Produced Water
Recovered: 325 bbls Produced Water

The release was caused by an alarm failure which resulted in a tank overflowed and occurred within the falcon lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2407 Pecos Ave.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Bratcher, Mike, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Monday, January 18, 2016 11:41 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification) COLT STATE SWD #004 (30-015-41401)

Mr. Bratcher,

COG Operating LLC is reporting a release on the COLT STATE SWD #004 (30-015-41401)
Unit D Section 5 Township 25S Range 28E
The release occurred at 12:00 pm on 1/16/2015.
Released: 325 bbls Produced Water
Recovered: 325 bbls Produced Water

The release was caused by an alarm failure which resulted in a tank overflowed and occurred within the falcon lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo
Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.