



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pSAD1327750882

1RP - 2969

DEVON ENERGY PRODUCTION COMPANY, LP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
OCT 04 2013
RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy	Contact Kenny Kidd
Address P.O. Box 250, Artesia, NM 88211	Telephone No. 575-748-3371
Facility Name Mad Dog 15 Federal Com #1	Facility Type Oil Well

Surface Owner	Mineral Owner	API No. 30-025-36778
---------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	23S	34E	660	SOUTH	660	EAST	LEA

Latitude 32.7271300239255 Longitude -103.909386055786

NATURE OF RELEASE

Type of Release Spill PRODUCED WATER SKRL 10/4/13	Volume of Release 20 bbls	Volume Recovered 0
Source of Release Water transfer line leak	Date and Hour of Occurrence 09/27/2013, 12:00pm	Date and Hour of Discovery 09/27/2013, 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trish Badbear BLM/ Jeff Leking OCD	SKRL 10/4/13
By Whom? Lynn Smith, Assistant Foreman	Date and Hour 9/27/2013, BLM 2:31pm, OCD 2:40pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW = 285' SKRL 10/04/13

Describe Cause of Problem and Remedial Action Taken.*
At the Mad Dog 15 -1, Lease Operator found a 20 barrel water leak on water transfer line .

Describe Area Affected and Cleanup Action Taken.*
Lease operator went to the Mad Dod 15 fed com # 1 and found the water transfure line had a hole and put 20 BBLS of produced water across an area of 3' X 150'. All water soaked in the ground. None was recovered. The water line was cut and re-welded and put back into production.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature: <i>Graciela C. Bustamante</i>		<i>Jeffrey Leking</i> Approved by Environmental Specialist Environmental Specialist	
Printed Name: Graciela C. Bustamante			
Title: Field Admin. Tech		Approval Date: 10/04/13	Expiration Date: 12/04/13
E-mail Address: Gracie.Bustamante@dvn.com		Conditions of Approval: DELINQUATE &	Attached <input type="checkbox"/>
Date: 10/02/2013 Phone: 575-746-5561		REMEDIATE PER OCD GUIDELINES	IRP-10-13-2969

* Attach Additional Sheets If Necessary

SUBMIT FINAL C-141 BY 12/04/13

4