



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1603944637

1RP - 4165

BASIC ENERGY SERVICES, LP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
JAN 22 2014
RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Basic Energy Services	Contact	David Alvarado
Address	PO Box 10460, Midland TX 79702	Telephone No.	575-746-2072
Facility Name	Eunice No# 001 BW -002	Facility Type	Brine Station
Surface Owner	Mineral Owner	API No.	3002526884

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	34	21S	37E	630	South	2427	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Brine Water	Volume of Release	130 barrels	Volume Recovered	110 barrels
Source of Release	broken Well head	Date and Hour of Occurrence	1/9/2014	Date and Hour of Discovery	1:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mark Hoskins		
By Whom?	Beto Gonzalez	Date and Hour	1:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Broken Well Head, replace well head → or hole thing?

white paint broken?

Describe Area Affected and Cleanup Action Taken.*

Spill inside berms. Loss of 130 barrels. Recovered 110 barrels with vacuum truck. Will clean effected area

Del. B Rem

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Mark Hoskins*
Printed Name: Mark Hoskins
Title: District Manager
E-mail Address: mark.hoskins@basicenergyservices.com
Date: 1/9/14 Phone: 575-736-1364

APPROVED
Approve
Approval Date: 2/10/16 | Expiration Date:
Conditions of Approval:
Attached

* Attach Additional Sheets If Necessary

RP 41165