



# AE Order Number Banner

## Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



**App Number: pKJ1604046120**

**1RP - 3070**

**APACHE CORP**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SEP 07 2010

HOBBSOCD

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name RedTag #1	Facility Type Production well
Surface Owner City of Hobbs	Mineral Owner State of NM
Lease No. 30-025-35333	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	2	21S	38E	2460'	FSL	2310'	FEL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Hydrocarbon/Produced Water	Volume of Release 5	Volume Recovered 3
Source of Release 1" ball valve	Date and Hour of Occurrence 07/31/2010 1130am	Date and Hour of Discovery Same
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Natalie Gladden	Date and Hour 08/03/2010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

WATER @ 75'

Describe Cause of Problem and Remedial Action Taken.\*  
1" ball valve at wellhead had a pinhole leak due to corrosion.

Describe Area Affected and Cleanup Action Taken.\*  
Fluid was released on location pad, no fluid in the pasture area. The contamination was excavated and hauled to Sundance Disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor: <i>Jeffrey Yelimo</i> Environmental Specialist	
Title: EHS Environmental Tech	Approval Date: 09/07/10	Expiration Date: 11/08/10
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 11/08/10	Attached <input type="checkbox"/>
Date: 08/15/2010 Phone: 575-390-4186	VRF-06-14-3070	

\* Attach Additional Sheets If Necessary