

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESTA DISTRICT

Form C-141
Revised August 8, 2011

FEB 11 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1604626856 **OPERATOR** Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SALADA VISTA 36 STATE #003H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: State	API No. 30-015-41157
------------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	31	19S	31E	1980'	North	180'	West	Eddy

Latitude 32.6186066 Longitude -103.9164963

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 200 bbls	Volume Recovered: 185 bbls
Source of Release: Check Valve	Date and Hour of Occurrence: 1/29/2016 6:45 am	Date and Hour of Discovery: 1/29/2016 6:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo Davis	Date and Hour: 1/29/2016 4:50 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a check valve on the roll line causing circulating pump pumped oil into the containment. Vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a lined facility. The facility will be cleaned and impacted gravel removed and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs</i>	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Robert Grubbs	Approval Date: <i>2/15/16</i>	Expiration Date: <i>NIA</i>
Title: Senior Environmental Coordinator	Conditions of Approval:	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: February 12, 2016 Phone: 432-230-0077	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 3/15/16

2RP-3553

Patterson, Heather, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Friday, February 12, 2016 1:10 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; 'james_amos@blm.gov' (james_amos@blm.gov); stucker@blm.gov
Cc: 'agroves@slo.state.nm.us'; 'dvstrang@slo.state.nm.us'; Martin, Ed; Naranjo, Mark M.
Subject: (C-141 Initial) SALADA VISTA 36 STATE #003H
Attachments: 1-29-2016 Salada Vista 36 State #3H (TB) Initial.pdf

MR. BRATCHER,

ATTACHED IS A C-141 INITIAL FOR YOUR CONSIDERATION. PLEASE FEEL FREE TO CONTACT ME IF YOU HAVE ANY QUESTIONS OR CONCERNS.

THANK YOU,

**ROBERT GRUBBS JR.
SR. ENVIRONMENTAL COORDINATOR
432.683.7443 (MAIN)
432.818.2369 (DIRECT)
432.661.6601 (CELL)
432.221.0892 (FAX)
RGRUBBS@CONCHO.COM
MAILING ADDRESS:
ONE CONCHO CENTER
600 W. ILLINOIS AVENUE
MIDLAND, TEXAS 79701**

CONFIDENTIALITY NOTICE: THE INFORMATION IN THIS EMAIL MAY BE CONFIDENTIAL AND/OR PRIVILEGED. IF YOU ARE NOT THE INTENDED RECIPIENT OR AN AUTHORIZED REPRESENTATIVE OF THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY REVIEW, DISSEMINATION OR COPYING OF THIS EMAIL AND ITS ATTACHMENTS, IF ANY, OR THE INFORMATION HEREIN, IS PROHIBITED. IF YOU RECEIVED THIS EMAIL IN ERROR, PLEASE IMMEDIATELY NOTIFY THE SENDER BY RETURN EMAIL AND DELETE THIS EMAIL FROM YOUR SYSTEM. THANK YOU.



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

Patterson, Heather, EMNRD

From: Amanda Trujillo Davis <ATrujillo@concho.com>
Sent: Friday, January 29, 2016 4:50 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Subject: (Notification) Salada Vista 36 State #3H (30-015-41157)

Mr. Bratcher,

COG Operating LLC is reporting a release on the Salada Vista 36 State #3H (30-015-41157)
Unit E Section 31 Township 19S Range 31E
The release occurred at 6:45 am on 1/29/2016.
Released: 200 bbls Oil
Recovered: 185 bbls Oil

The release was caused by a check valve failure on a roll line from oil tank. This release occurred within the lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.