

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 17 2016

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Sub-RECEIVED appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1404938284

OPERATOR

Initial Report Final Report

Name of Company: Lime Rock Resources II-A, LP <i>277558</i>	Contact: Mike Barrett
Address: 1111 Bagby Street Ste. 4600, Houston, TX 77002	Telephone No. 575-623-8424
Facility Name: West Redlake Water Station #1	Facility Type:

Surface Owner: BLM	Mineral Owner: Federal	API No. <i>30-015-28443</i>
--------------------	------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	7	18S	27E					Eddy

Latitude 32.768991 Longitude -104.314224

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 1100bbls	Volume Recovered: 1040bbls
Source of Release: Flowline	Date and Hour of Occurrence: 2/14/2016	Date and Hour of Discovery: 2/15/2016 9:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD Shelly Tucker-BLM, voicemail	
By Whom? Kimberly Wilson-Talon/L.P.F.	Date and Hour: 2/15/16 3:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A flowline ruptured resulting in the release of approximately 1,100bbls of produced water. Upon discovery the line was shut in and repaired. Vacuum trucks were immediately dispatched to the location and were able to recover approximately 1,040bbls of fluid. The heavily impacted soil was scraped up to prevent further spread of fluid.

Describe Area Affected and Cleanup Action Taken.* The fluid remained within the berms of the West Redlake #1 location. Talon/L.P.F. mobilized personnel to conduct a site assessment and collect soil samples within the impacted area. Upon receipt of analytical data from the soil sampling event a remediation work plan will be generated and submitted to NMOCD and BLM for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mike Barrett</i>	OIL CONSERVATION DIVISION	
Printed Name: Mike Barrett	Signed By: <i>Mike Barrett</i> Approved by Environmental Specialist	
Title: Production Supervisor	Approval Date: <i>2/18/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/17/2016 Phone: 575-623-8424		

* Attach Additional Sheets If Necessary

2RP-3558

Bratcher, Mike, EMNRD

From: Kimberly M. Wilson <kwilson@talonlpe.com>
Sent: Wednesday, February 17, 2016 11:58 AM
To: Bratcher, Mike, EMNRD; Tucker, Shelly
Cc: Michael Barrett; David Adkins
Subject: West Redlake Water Station #1 Battery
Attachments: Signed initial C-141.pdf

Mike,

Attached is the initial C-141 for the above location.

Thanks

Kimberly M. Wilson
Project Manager
408 West Texas Avenue
Artesia, New Mexico 88210
(575) 746.8768 office
(575) 616.4023 direct
(575) 602.3826 cell
(866) 742.0742 emergency
Email: kwilson@talonlpe.com
Web: www.talonlpe.com



Inc. 500



ICIC

BusinessWeek