

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB16051654667 OPERATOR Initial Report Final Report

Name of Company	RKI E&P, LLC <i>246289</i>	Contact	Taylor Jones
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	539-573-7558
Facility Name:	Ross Draw Unit 42	Facility Type :	Oil and Gas Well
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30-015-42945

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	26S	30E	1980	FSL	1800	FWL	Eddy

Latitude: 32.02600 Longitude: -103.87139

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 13 Bbbls	Volume Recovered: 11 Bbbls
Source of Release: Polish rod Liner	Date and Hour of Occurrence: 2/20/16 - 10:00 MT	Date and Hour of Discovery: 2/20/16 - 10:00 MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NM OIL CONSERVATION	
By Whom?	Date and Hour:	ARTESIA DISTRICT
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A	RECEIVED	
Describe Cause of Problem and Remedial Action Taken.* Polish Rod liner became loose, allowing the release of crude oil and produced water. Crew shut well in and tightened the liner.		
Describe Area Affected and Cleanup Action Taken.* All fluids remained on well site. Vacuum truck dispatched to recover all free standing fluids. Affected soil on well pad to be dug and hauled to disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Taylor Jones</i>	OIL CONSERVATION DIVISION	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Safety Specialist II	Approval Date: 2/25/16	Expiration Date: N/A
E-mail Address: taylor.jones@wpenergy.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	Attached <input type="checkbox"/>
Date: 02/22/16 Phone: 539-573-7558	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 3/26/16

2RD-3564

Patterson, Heather, EMNRD

From: Jones, Taylor <Taylor.Jones@wpxenergy.com>
Sent: Monday, February 22, 2016 2:56 PM
To: Patterson, Heather, EMNRD
Cc: stucker@blm.gov; Laird, Zack
Subject: RE: RKI E&P Spill Notification
Attachments: NM_RDU42_InitialC141(022216)-signed.pdf

Heather,

Please see attached OCD form C-141 for a spill occurring at the RKI (Now WPX Energy) operated Ross Draw Unit 42, API: 30-015-42945

Please let me know if you have any questions.

Regards,

Taylor Jones
Safety Specialist II
WPX Energy, Inc.
210 Park Avenue, Suite 700
Oklahoma City, OK 73102
539-573-7558 (o) | 405.326.0791 (m)
NEW: taylor.jones@wpxenergy.com