

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

FEB 24 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1405735051

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name Perdomo BMP State Com. #1	Facility Type Battery

Surface Owner State	Mineral Owner State	API No. 30-015-36499
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter L	Section 24	Township 24S	Range 27E	Feet from the 1650	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.20029 Longitude 104.15024

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 110 B/PW	Volume Recovered 110 B/PW
Source of Release Transfer Pump	Date and Hour of Occurrence 2/12/2016; AM	Date and Hour of Discovery 2/12/2016; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 2/12/2016; AM (e-mail) <i>7:13am *e-mail</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The transfer pump seal failed, causing the pump to lock up and not send produced water to the SWD. Vacuum truck(s) were called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 20' X 80' (inside bermed and lined battery). All of the produced water recovered. The transfer pumps were switched and the well/battery is back in operation. Depth to Ground Water: 50-99' (approx. 70', Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on recovery of all produced water and the battery is bermed/lined and liner intact, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Asher</i>	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Supervisor	Approval Date: <i>2/25/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: February 24, 2016	2RP-	

* Attach Additional Sheets If Necessary

2RP-3567

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Wednesday, February 24, 2016 11:50 AM
To: Bratcher, Mike, EMNRD
Subject: Form C-141 (Initial/Final Report)
Attachments: Perdomo BMP State Com 1 (02122016 C141 Initial Final).pdf

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Health & Environmental Department
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)
Yates Safety Begins With YOUR Safety

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, February 12, 2016 7:13 AM ✕
To: Bratcher, Mike; EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; NMSLO (Carlsbad/Ion Dolly); NMSLO (Hobbs/Amber Groves); NMSLO (Hobbs/Mathew Hagman); Naranjo, Mark M.; NMSLO (Santa Fe/Dana Vackar Strang)
Cc: IncidentReportingNM; Amber Griffin; Chase Settle; Katie Parker; Veronica Alvarado
Subject: Release Notification (Perdomo BMP State Com. #1)

Yates Petroleum Corporation is reporting a release at the following location (2/12/2016, 6:45 AM).

Perdomo BMP State Com. #1
30-015-36499
Section 24, T24S-R27E
1650 FSL & 660 FWL
Eddy County, New Mexico

Released: 350 B/ PW; Recovered: In progress.

Cause of the release was from a pump locking up, causing the tanks to overrun. **All released produced water was contained within the lined/bermed battery.** Vacuum truck(s) have been called. A Form C-141 with complete information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
