

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

**FEB 29 2016**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

*NAB/1601/055123*

*6137*

**OPERATOR**

Initial Report  Final Report

<b>Name of Company</b> Devon Energy Production Company	<b>Contact</b> Enrique Campos, Production Foreman
<b>Address</b> 6488 Seven Rivers Hwy Artesia, NM 88210	<b>Telephone No.</b> 575-513-1933
<b>Facility Name</b> Burton Flat Deep Unit #8	<b>Facility Type</b> Oil

<b>Surface Owner</b> Federal	<b>Mineral Owner</b> Federal	<b>API No</b> 30-015-20959
------------------------------	------------------------------	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	27	20S	28E	660	South	1980	East	Eddy

**Latitude:** N 32.5390663 **Longitude:** W 104.1635818

**NATURE OF RELEASE**

<b>Type of Release</b> Produced water	<b>Volume of Release</b> 10 BBLS	<b>Volume Recovered</b> 5 BBLS
<b>Source of Release</b> ½ inch ball valve	<b>Date and Hour of Occurrence</b> 2/25/2016 @ 10:50am	<b>Date and Hour of Discovery</b> 2/25/2016 @ 10:50am
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> OCD-Mike Bratcher BLM-Jim Amos	
<b>By Whom,</b> Gilbert Sanchez, Assistant Production Foreman	<b>Date and Hour</b> OCD- 2/25/2016 @ 2:47pm BLM- 2/25/2016 @ 2:51pm	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse</b> N/A	

**If a Watercourse was Impacted, Describe Fully.\*** N/A


**Describe Cause of Problem and Remedial Action Taken.\***

½ inch ball valve on produced water load line was left open resulting in a release of 10 BBLS of produced water. Ball valve was immediately closed to prevent further release.

**Describe Area Affected and Cleanup Action Taken.\***

10 BBLS of produced water was released from the ½ inch ball valve on the water load line on the water tank located on the West side. All 10 BBLS produced water released remained on location. Vacuum truck recovered approximately 5 BBLS of the released produced water. The released produced water flowed in an Easterly direction affecting an area approximately 50 feet by 15 feet. An Environmental Agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> Dana DeLaRosa	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Dana DeLaRosa	<b>Approved by Environmental Specialist:</b> 	
<b>Title:</b> Field Admin Support	<b>Approval Date:</b> 2/29/16	<b>Expiration Date:</b> N/A
<b>E-mail Address:</b> Dana.Delarosa@dvn.com	<b>Conditions of Approval:</b>	
<b>Date:</b> 2/29/2016 <b>Phone:</b> 575.746.5594	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN:</b> 3/31/16	

\* Attach Additional Sheets If Necessary

2RP-3570

**Patterson, Heather, EMNRD**

---

**From:** DeLaRosa, Dana <Dana.DeLaRosa@dvn.com>  
**Sent:** Monday, February 29, 2016 11:06 AM  
**To:** jamos@blm.gov; stucker@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD  
**Subject:** Burton Flat Deep Unit 8\_ 10 BBLS PW\_2.25.16  
**Attachments:** Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 4 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 5 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 6 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 7 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 8 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_ 10 BBLS PW\_2.25.16\_GIS Image.pdf; Burton Flat Deep Unit 8\_ 10 BBLS PW\_2.25.16\_Initial C-141.doc; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 1 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 2 of 8\_2.25.16.jpg; Burton Flat Deep Unit 8\_10BBL PW Release\_Pic 3 of 8\_2.25.16.jpg

**Categories:** printed

Good Morning,

Attached is the initial C141, GIS Image and photos for the 10BBLS Produced Water release that occurred at the Burton Flat Deep Unit 8 on 2.25.2016. The red dot on the GIS Image represents the approximate origin of release.

Thank you in advance,

*Dana DeLaRosa*

Field Admin Support  
Production  
B-Schedule



Devon Energy Corporation  
PO Box 250  
Artesia, NM 88211  
575-746-5594

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.