




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pGRL1033432867

1RP - 2664

APACHE CORP

3/1/2016

MAR 01 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
AUG 04 2010
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address PO Box 1849 Eunice, NM 88231	Telephone No. 575-390-4186
Facility Name South Eunice Seven Rivers Queen Unit	Facility Type Water Flood
Transfer line (nearest well SEU #402)	

Surface Owner Deck Estate	Mineral Owner NMOCD	Lease No. 30-025-09159
---------------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	35	22S	36E	660'	FNL	2310'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 15-20bbls	Volume Recovered 0bbls
Source of Release Transfer Line	Date and Hour of Occurrence 06/29/2010 ?	Date and Hour of Discovery 06/29/2010 1156am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 06/29/2010 215pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 140'

Describe Cause of Problem and Remedial Action Taken.*

This line was buried bgs but when surfaced, lease was shut in, clamp was put on line and lease turned back on. The entire 1.3 miles of steel line has been replaced with NUPI Polyline. The saturated soil was immediately excavated and hauled to Sundance Services.

Describe Area Affected and Cleanup Action Taken.*

The pasture area was cleared of all vegetation and contaminated soil was hauled to Sundance Disposal. Final samples were taken and location was backfilled. Closure document to follow.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by ENV. ENGINEER District Supervisor: <i>Jeffrey Blum</i>	
Title: EHS Environmental Tech	Approval Date: 08/04/10	Expiration Date: 10/04/10
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C-141 BY 10/04/10,	Attached <input type="checkbox"/>
Date: 07/18/2010 Phone: 575-390-4186		IRP-11-10-2664

* Attach Additional Sheets If Necessary