



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1607047230

1RP - 4207

CAMERON OIL & GAS INC

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Name of Company: <u>Cameroon Oil & Gas Inc</u>		OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Address: <u>PO Box 1455 Roswell NM 88202</u>		Contact: <u>G. DAVID Sweeney</u>	
Facility Name: <u>Federal Co Well #1</u>		Telephone No.: <u>575-420-1108 cell 575-427-3284 office</u>	
Surface Owner: <u>HORSCHLAGARY CAUINNESS</u>		Facility Type: <u>PRODUCING OIL WELL</u>	
Mineral Owner: <u>BLM</u>		API No.: <u>30-025-27739</u>	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<u>L</u>	<u>6</u>	<u>18S</u>	<u>33E</u>	<u>1650</u>	<u>SOUTH</u>	<u>1050</u>	<u>WEST</u>	<u>LEA</u>

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: <u>OIL</u>	Volume of Release: <u>120 Bbls</u>	Volume Recovered: <u>70 Bbls</u>
Source of Release:	Date and Hour of Occurrence:	Date and Hour of Discovery: <u>7-22-2013</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3x2 Swedge ON BACK OF STOCK TANK STARTED LEAKING, WHEN NOTIFIED OF LEAK, SENT A VACUUM TRUCK AND BACK HOLE TO START CLEAN-UP

Describe Area Affected and Cleanup Action Taken.*

Inside water basin, ON LOCATION, AND INTO PAVEMENT

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>G. David Sweeney</u>	Appr:
Printed Name: <u>G. DAVID Sweeney</u>	Appr:
Title: <u>Vice President</u>	Appr:
E-mail Address: <u>dsweeney@cameroonoil.com</u>	Condi:
Date: <u>7-26-2013</u> Phone: <u>575-420-1108</u> <u>575-427-3284</u>	

APPROVED

3/10/16

Attached

1 RP-4207

* Attach Additional Sheets If Necessary

HOBBS OCD

SEP 27 2013

RECEIVED