




AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pKJ1607051343

1RP - 4210

LINN OPERATING, INC.

RECEIVED

MAR 27 2012

HOBBSOCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action**OPERATOR** Initial Report Final Report

Name of Company: Linn Operating	Contact: Gary Wink
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575738-1739
Facility Name: CMU B Battery/ CMU #65	Facility Type: Central Tank Battery
Surface Owner: State	Mineral Owner: State
API No.: 3002501483	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	19	17S	33E	2310	S	2379	W	Lea

Latitude: 32.8190921995382 Longitude: -103.703547926365

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 175	Volume Recovered: 150
Source of Release: Tank	Date and Hour of Occurrence: 03/24/2012 10:30am	Date and Hour of Discovery: 03/24/2012 11am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker- NM OCD	
By Whom? Gary Wink	Date and Hour 03/24/2012 10:45am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Electricians were working at Tank Battery had HOA off while working and forgot to turn back on.

Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Gary W. Wink</i>	Approved by District Supervisor:	
Printed Name: Gary W. Wink	Approval Date:	Expiration Date:
Title: Production Foreman	Conditions of Approval:	
E-mail Address: gawink@linenergy.com	Attached <input type="checkbox"/>	
Date: 03-27-2012	Phone: 575-390-3477	

* Attach Additional Sheets If Necessary